

Figure - Bug #118172

【IOVDEV-29804】【内部】【VC1】【0095】【台架】【EE环境】【副屏】【蓝牙】副屏蓝牙与支持设备进行配对连接时，不点击弹窗的“配对”按钮，自动取消弹窗时间为30s，

2023-05-23 11:40 - CDTS_TEST 王成

Status:	CLOSED	Start date:	2023-05-23
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0095
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-23
Test Type:	ST	Root cause:	需求未实现。
Description			
【环境信息】EE环境			
【问题出现时间】：20230522 09：51			
【前提条件】：副屏上电，蓝牙耳机设备已激活			
【操作步骤】			
1.打开蓝牙			
2.点击蓝牙耳机设备			
3.点击蓝牙耳机设备名称			
【实际结果】			
1.配对弹窗显示30s后关闭			
【期望结果】			
1.配对弹窗显示15s后关闭			

History

- #1 - 2023-05-23 13:40 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
 - Assignee changed from CD FW 曹覃刚 to CD FW-廖涛
- #2 - 2023-05-23 14:10 - CDTS_TEST 王成
- File 蓝牙UE-未点连接15秒关闭界面.jpg added
- #3 - 2023-05-23 22:04 - IoT scm
- Gerrit Merge Information：

ID	Project	Branch	Uploader
202157	general/platform/vendor/qcom-opensource/system/bt	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Modify bluetooth pairing timeout to 15s.TC-RID: 1201-0201801IssueID: TS-R-BUG-118172Change-Id: I56bd6879beb852a42cff410b9999da9d9c00efde			

#4 - 2023-05-23 22:05 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_TEST 王成
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-23
- Root cause set to 需求未实现。

■ Current conclusion

已处理，代码已入库。

■ My analysis

需求未实现。

■ Next action

测试验证。

#5 - 2023-06-02 15:21 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在106版本验证通过

#6 - 2023-06-02 15:21 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED

Files			
蓝牙UE-未点连接15秒关闭界面.jpg	188 KB	2023-05-23	CDTS_TEST 王成