

Figure - Bug #118283

【IOVDEV-30863】 【内部】 【VC1】 【00100】 【台架】 【EE环境】 【副屏】 副屏蓝牙连接手柄时一直处在连接状态

2023-05-26 19:30 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-05-26
Priority:	High	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	LC	Estimated time:	0.00 hour
Target version:		Found Version:	【中控版本号】 : 03.02.0082.C101 【副屏版本号】 : 01.00.0100.c103
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
环境信息】EE环境			
【问题出现时间】 : 20230526 16 : 52			
【前提条件】 : 副屏上电 , 中控已连接			
【操作步骤】			
1.搜索蓝牙手柄配对连接			
【实际结果】			
1.界面显示与蓝牙手柄一直处在正在连接状态			
【期望结果】			
1.连接成功			
【备注】 :			
【当前开机次数】 : 132			
【应用版本】 :			
【硬件版本号】 : MADEL:SE3215			
VIN:HRYTTESTVINMGM401			
【中控版本号】 : 03.02.0082.C101			
【副屏版本号】 : 01.00.0100.c103			

History

#1 - 2023-05-26 19:31 - CDTs_Test 吴诗雨

ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_118283

- #2 - 2023-05-26 19:33 - CD FW-廖涛
- Category changed from CD-FW to LC
 - Status changed from New to ASSIGNED
 - Assignee changed from CD FW-廖涛 to CD LC 陶洪普

Hi, 洪普 :

麻烦帮忙分析下这个问题。

#3 - 2023-05-30 17:32 - 短距组_SSRDCNJ 蒋俊杰

05-26 16:53:05.577 1002 1847 26252 D BluetoothHidHostService: connect: 98:B6:E9:E0:80:56
05-26 16:53:09.645 1000 1530 1530 D CompanionDeviceManagerService: 98:B6:E9:E0:80:56 disconnected w/ reason: (1100) Local request
【结论】：车机本地终止连接，没有HCIlog无法进一步分析原因
【下一步计划】：测试复现提供hciolog

#4 - 2023-05-30 19:44 - CDTS-TEST 周婷
- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD LC 陶洪普 to CDTS_Test 吴诗雨

请帮忙进行复现或者联系客户那边复现抓取log

#5 - 2023-06-03 14:44 - CD TEST-方永红

6.3
客户复现中

#6 - 2023-06-09 20:13 - CDTS_Test 吴诗雨

6.9
客户未复现

#7 - 2023-07-04 17:54 - CDTS_TEST 王成
- Status changed from NEED_INFO to RESOLVED

客户反馈多个版本未复现，BUG已关闭

#8 - 2023-07-04 17:54 - CDTS_TEST 王成
- Status changed from RESOLVED to VERIFIED

#9 - 2023-07-04 17:54 - CDTS_TEST 王成
- Status changed from VERIFIED to CLOSED

Files			
video_1685091226.mp4	8.69 MB	2023-05-26	CDTS_Test 吴诗雨