

Figure - 开发 Dev #118394

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务

【MK】【008】【BOOT】【TC-RID: 1201-0100702】Selinux错误处理

2023-05-31 16:30 - CD TPM-王祥林

Status:	New	Start date:	2023-05-31
Priority:	Normal	Due date:	
Assignee:	CD TPM-王祥林	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
通过monkey日志过滤avc关键字，来fix selinux错误			

History

#1 - 2023-05-31 20:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203891	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	laiyx0702@thundersoft.com
BSP:Security:Fix selinux erroradd some policyTC-RID: 1201-0100702IssueID: TS-R-DF-118394Change-Id: lbed83e84966c3273902a0cf9937e623fa8a45ac8			

#2 - 2023-05-31 20:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203892	general/vendor/thundercomm/products/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	laiyx0702@thundersoft.com
BSP:Security:Fix selinux erroradd some policyTC-RID: 1201-0100702IssueID: TS-R-DF-118394Change-Id: l3ff071b60213e58f6b274deddd95399280d889b1			

#3 - 2023-05-31 20:45 - CD BSP赖永惺

Hi ALL

部分修改已入库，等待新版本Monkey测试结果

<https://dev.thundercomm.com/gerrit/q/topic:FIGURE-MK-SELINUX>

Thanks

Yongxing

#4 - 2023-06-09 18:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
206043	general/vendor/thundercomm/products/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	laiyx0702@thundersoft.com
<p>BSP:Security:Add new policy for various domainsadd some policyTC-RID: 1201-0100702IssueID: TS-R-DF-118394Change-Id: I8ccca55832e317ca78139f1d504695b765fee517</p>			

#5 - 2023-07-04 16:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212036	general/vendor/thundercomm/products/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	laiyx0702@thundersoft.com
<p>BSP:Security:Fix selinux erroradd some policyTC-RID: 1201-0100702IssueID: TS-R-DF-118394Change-Id: I36773823ae5f460e91cebe61aaa637299fdd37f0</p>			

#6 - 2023-07-10 17:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213609	general/vendor/thundercomm/products/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
<p>BSP:Security:Fix selinux erroradd some policyTC-RID: 1201-0100702IssueID: TS-R-DF-118394Change-Id: I36773823ae5f460e91cebe61aaa637299fdd37f0(cherry picked from commit 3f8beaff95092ed8a9d3cd56fa3e000a2e55cb6d)</p>			