

Status:	CLOSED	Start date:	2023-05-31
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	【中控版本号】：03.02.0086.C102
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-02
Test Type:	ST	Root cause:	音乐控制器 UI 适配问题。
Description			
环境信息】EE环境			
【问题出现时间】：20230531 17：25			
【前提条件】：副屏上电，中控已连接			
【操作步骤】			
1.副屏设置调节字体最大			
2.播放本地歌曲			
3.下滑手势进入控制中心查看音乐名称显示			
【实际结果】			
1.设置字体调节最大时，控制中心音乐名称显示不完整			
【期望结果】			
1.设置字体调节最大时，控制中心音乐名称正常显示			
【备注】：			
【当前开机次数】：143			
【应用版本】：			
【硬件版本号】：			
VIN:HRYTTESTVINMGM401			
【中控版本号】：03.02.0086.C102			
【副屏版本号】：01.00.0100.c103			

History
#1 - 2023-06-01 18:19 - CD FW-廖涛
■ Current conclusion
已处理，代码已提交。
■ Next action
等待 Review 入库。

#2 - 2023-06-02 17:37 - CD FW-廖涛

- Status changed from New to ASSIGNED
- % Done changed from 0 to 100
- Degrated changed from -- to No
- Root cause set to 音乐控制器UI 适配问题。

#3 - 2023-06-02 19:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
204064	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SystemUI: Fix music controller panel problem.TC-RID: 1201-0201903IssueID: TS-R-BUG-118404Change-Id: I1a9a25e3b27282581cca7d001d49822b3f00ce1b			

#4 - 2023-06-02 19:21 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-06-02

■ Current conclusion

已处理，代码已入库。

■ Next action

测试验证。

#5 - 2023-06-06 14:26 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在01.00.0108.C104版本验证通过

#6 - 2023-06-12 16:27 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
4a000a76-3d43-4fad-a196-b2b268943a29.jpg	74.1 KB	2023-05-31	CDTS_Test 吴诗雨