

Status:	CLOSED	Start date:	2023-06-01
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTs 唐霞	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	01.00.100.c103
Need_Info:	--	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Frequently	Root cause:	AOSP 原生逻辑。
Test Type:	User Experience		
Description			
环境信息】EE环境			
【问题出现时间】：20230529 20:46			
【前提条件】：副屏上电			
连接中控、时间与中控时间同步			
网络连接情况正常			
【操作步骤】			
1.副屏点击设置页-已连接设备选项			
2.已连接设备选项-与新设备匹配，搜索蓝牙鼠标名称并连接			
3.蓝牙鼠标连接成功，点击进入蓝牙设备详情页-点击重命名选项			
【实际结果】			
1.蓝牙鼠标连接成功，点击设备进入详情页，点击重命名选项，输入内容为空，点击重命名按钮无提示			
【期望结果】			
1.蓝牙鼠标连接成功，点击设备进入详情页，点击重命名选项，输入内容为空，提示输入法不能为空（举例）			
【备注】：			
当前开机次数】：副屏当前开机第143次			
【百度应用版本】：10.6.1003.9			
【硬件版本号】：			
【中控版本号】：03.02.0086.C102			
【副屏版本号】：01.00.100.c103			
IDCM VIN：HRYTTESTVINMGM402			
体验了问题，建议优化			
SN：HRYTTESTVINID0402			

History

#1 - 2023-06-01 19:39 - CD FW-廖涛

- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from New to NEED_INFO
- Assignee changed from CD FW 曹覃刚 to 物联网测试组_CDTS 唐霞
- Root cause set to AOSP 原生逻辑。

■ Current conclusion

原生逻辑，无需处理。

名称修改输入框逻辑：

1. 名称未变更或变更后无效（空白），则不允许点击确认按钮进行确认；
2. 输入超过限制时，新输入的字符不插入到输入框中；

■ Next action

测试确认并同步客户。

#2 - 2023-06-03 17:04 - CD TEST-方永红

- Status changed from NEED_INFO to RESOLVED
- Resolution changed from -- to WONTFIX

#3 - 2023-06-03 17:04 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#4 - 2023-06-03 17:05 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED