

Status:	CLOSED	Start date:	2023-06-01
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	ro.build.display.vc1.id]: [01.00.0106.C104]
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-05
Test Type:	Free Test	Root cause:	蓝牙名称长度限制调整后，旧数据导致的异常。
Description			
前置条件：车机上电（KL30ON，KL15 ON，已连接中控和功放，可正常输出声音）			
操作步骤：打开设置-已连接的蓝牙设备-其他设备，修改鼠标和键盘的蓝牙设备名称			
预期结果：设置闪退			
实际结果：可成功修改蓝牙设备名			

History

- #1 - 2023-06-01 19:43 - SZTS_TEST 邹涛
- File tlog_35f43216_000166_1111002032.tar - 副本.gz added
- File tlog_35f43216_000166_1111002032.tar.gz added
- File tlog_35f43216_000166_1111002629.tar.gz added
- File tlog_35f43216_000166_1111004313.tar.gz added
- File tlog_35f43216_000166_1111004559.tar.gz added
- File tlog_35f43216_000169_1111010149.tar.gz added
- File tlog_35f43216_000173_1111023055.tar.gz added
- File tlog_35f43216_000173_1111025055.tar.gz added
- #2 - 2023-06-01 19:45 - SZTS_TEST 邹涛
- File deleted (tlog_35f43216_000166_1111002032.tar - 副本.gz)
- #3 - 2023-06-01 23:07 - CDTS-TEST 周婷
- Category set to LC
- #4 - 2023-06-02 16:57 - 短距组 SSRDCNJ 蒋俊杰
- 06-01 01:38:51.844 2419 2419 D AndroidRuntime: Shutting down VM
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: FATAL EXCEPTION: main
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: Process: com.qualcomm.qti.devicestatisticsservice, PID: 2419
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: java.lang.NoClassDefFoundError: Failed resolution of: Landroid/hidl/manager/V1_0/IServiceNotification\$Stub;
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at com.qualcomm.qti.devicestatisticsservice.DeviceStatisticsService.onStartCommand(DeviceStatisticsService.java:83)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.app.ActivityThread.handleServiceArgs(ActivityThread.java:4640)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.app.ActivityThread.access\$2000(ActivityThread.java:248)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.app.ActivityThread\$H.handleMessage(ActivityThread.java:2092)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.os.Handler.dispatchMessage(Handler.java:106)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.os.Looper.loopOnce(Looper.java:201)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.os.Looper.loop(Looper.java:288)
- 06-01 01:38:51.845 2419 2419 E AndroidRuntime: at android.app.ActivityThread.main(ActivityThread.java:7880)

06-01 01:38:51.845 2419 2419 E AndroidRuntime: at java.lang.reflect.Method.invoke(Native Method)
06-01 01:38:51.845 2419 2419 E AndroidRuntime: at com.android.internal.os.RuntimeInit\$MethodAndArgsCaller.run(RuntimeInit.java:548)
06-01 01:38:51.845 2419 2419 E AndroidRuntime: at com.android.internal.os.ZygoteInit.main(ZygoteInit.java:1009)
06-01 01:38:51.845 2419 2419 E AndroidRuntime: Caused by: java.lang.ClassNotFoundException: android.hidl.manager.V1_0.IServiceNotification\$Stub
06-01 01:38:51.845 2419 2419 E AndroidRuntime: ... 11 more

未明确crash时间点，日志记录时间段未看到com.android.bluetooth进程crash。系统出现crash。

- 【结论】:非蓝牙测问题
- 【下一步计划】:测试确认crash具体时间点，设置或系统模块继续分析

#5 - 2023-06-05 11:12 - CD LC涂宇
- Status changed from New to ASSIGNED

#6 - 2023-06-05 16:45 - 短距组_SSRDCNJ 蒋俊杰
- Assignee changed from CD LC 陶洪普 to CD APP-王莹

#7 - 2023-06-05 19:48 - CDTs-TEST 周婷
- Assignee changed from CD APP-王莹 to CD FW-廖涛

#8 - 2023-06-05 21:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
204874	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix crash problem when change bluetooth device name.TC-RID: 1201-0201801IssueID: TS-R-BUG-118437Change-Id: I82ea38bb392b924ee158e594615b6415647553aa			

#9 - 2023-06-05 21:11 - CD FW-廖涛
- Category changed from LC to CD-FW
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to SZTS_TEST 邹涛
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-05
- Root cause set to 蓝牙名称长度限制调整后，旧数据导致的异常。

■ Current conclusion

已处理，代码已入库。

■ My analysis

蓝牙名称长度限制调整后，旧数据导致的异常。已做兼容处理。

■ Next action

测试验证。

#10 - 2023-06-06 17:35 - SZTS_TEST 邹涛
- Status changed from RESOLVED to VERIFIED

在01.00.0108.C104版本验证通过

#11 - 2023-06-06 17:35 - SZTS_TEST 邹涛
- Status changed from VERIFIED to CLOSED

Files			
tlog_35f43216_000166_1111002032.tar.gz	8.13 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000166_1111002629.tar.gz	8.37 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000166_1111004313.tar.gz	8.79 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000166_1111004559.tar.gz	9.42 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000169_1111010149.tar.gz	17.9 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000173_1111023055.tar.gz	27.2 MB	2023-06-01	SZTS_TEST 邹涛
tlog_35f43216_000173_1111025055.tar.gz	28.7 MB	2023-06-01	SZTS_TEST 邹涛