

Figure - Bug #118473
【IOVDEV-32206】 【内部】 【解决方案】 【VC1】 【0086】 【实车】 【EE环境】 副驾熄屏，直接下电，上电，副驾熄屏按钮一直高亮，实际亮屏；
2023-06-02 20:18 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-06-02
Priority:	High	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	03.02.0086.C102.03
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【出现时间】：2023.6.1 17：07：24 【前提条件】： 1、车机上电 【操作步骤】： 1、副驾熄屏， 2、直接下电， 3、上电， 【实际结果】： 副驾熄屏按钮一直高亮，实际亮屏； 【期望结果】： 应同步亮屏状态 【备注】：安卓日志已上云 【车架号】：LJD8BB3F9P0000385 【环境信息】：EE 【版本详情】：03.02.0086.C102.03 【复归方法】：无			

History

- #1 - 2023-06-02 20:19 - CDTs_Test 吴诗雨
- File screenshot-20230602-201859.png added
 - File screenshot-20230602-201923.png added
- 具体情况请看截图
- #2 - 2023-06-03 14:52 - CDFW-程天颖
- Status changed from New to NEED_INFO
 - Assignee changed from CDFW-程天颖 to CDTs_Test 吴诗雨

请提供副屏版本，与<熄屏状态下重启副屏，重启后，中控显示副屏熄屏，实际副屏亮屏>现象类似，需要确认是否是该问题修复后的版本
<https://share.thundersoft.com/redmine/issues/118229>

如果是修复前的版本，请使用新新版本进行测试，是否还有该问题

#3 - 2023-06-09 19:53 - CDTS_Test 吴诗雨
- Status changed from *NEED_INFO* to *RESOLVED*

jira bug已关闭

#4 - 2023-06-09 19:53 - CDTS_Test 吴诗雨
- Status changed from *RESOLVED* to *VERIFIED*

#5 - 2023-06-09 19:53 - CDTS_Test 吴诗雨
- Status changed from *VERIFIED* to *CLOSED*

Files				
1685708247029.zip	1.62 MB	2023-06-02	CDTS_Test 吴诗雨	
IOVDEV-32206.zip	3.13 MB	2023-06-02	CDTS_Test 吴诗雨	
screenshot-20230602-201859.png	269 KB	2023-06-02	CDTS_Test 吴诗雨	
screenshot-20230602-201923.png	194 KB	2023-06-02	CDTS_Test 吴诗雨	