

Status:	CLOSED	Start date:	2023-06-02
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	【中控版本号】：03.02.0086.C102
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-05
Test Type:	ST	Root cause:	自动亮度开启时，亮度调节值变更处理问题。

Description	
环境信息】EE环境	
【问题出现时间】：20230602 17：52	
【前提条件】：副屏上电，中控已连接	
【操作步骤】	
1.自动亮度开启	
2.点击亮度选项唤起亮度调节条	
【实际结果】	
1.自动亮度切换手动调节亮度时需要点击两次才能调节，第一次点击关闭自动亮度，第二次点击手动调节亮度才能成功	
【期望结果】	
1.自动亮度切换手动调节亮度时，只需点击一次亮度调节条就可以手动调节且自动亮度关闭	
【备注】：	
【当前开机次数】：151	
【应用版本】：	
【硬件版本号】：	
VIN:HRYTTESTVINMGM401	
【中控版本号】：03.02.0086.C102	
【副屏版本号】：01.00.0106（01.00.0104）	

History			
#1 - 2023-06-05 20:03 - IoT scm			
Gerrit Merge Information：			
ID	Project	Branch	Uploader
204765	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SystemUI: Don't update brightness value when auto brightness changed.TC-RID: 1201-0201903IssueID: TS-R-BUG-118476Change-Id: I251da3997508d899c82d61d23c44e7631a5b19cc			

#2 - 2023-06-05 20:08 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-05
- Root cause set to 自动亮度开启时，亮度调节值变更处理问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

自动亮度开启时，亮度调节值变更处理问题。

■ Next action

测试验证。

#3 - 2023-06-07 20:51 - CDTS_Test 吴诗雨

已同步

#4 - 2023-06-08 17:05 - SZTS_TEST 邹涛

在FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306080125版本验证不通过

#5 - 2023-06-09 15:22 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在 FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306090153版本验证通过

#6 - 2023-06-25 19:17 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
IOVDEV-32469.zip	3.58 MB	2023-06-02	CDTS_Test 吴诗雨