

Figure - Bug #118556
IOVDEV-32757【内部】【VC1】【0106】【台架】【EE环境】【副屏】【手势】第三方应用界面，屏幕左侧边缘向右滑动，无法退出应用，右向左滑相同
2023-06-05 20:53 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-05
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】：EE环境 【问题出现时间】：20230605 18:24，第202次开机 【前提条件】：已安装华为应用市场，打开华为应用市场主界面 【操作步骤】：1、屏幕左侧边缘向右滑动，重复3次 2、屏幕右侧边缘向左滑动，重复3次 【实际结果】 1、每次向右滑动，都会提示“再按一次退出” 2、每次向左滑动，都会提示“再按一次退出” 【期望结果】 再一次滑动，应用退出或到后台。若手势不可控制第三方应用，不应该提示“再按一次退出”。 【备注】：https://ofs.human-horizons.com/#/download/index/kEVmSHe9hyY%3D 华为应用市场版本 13.11.300 【副屏版本号】：01.00.0106.C104 【中控版本号】：03.02.0088.C103.02_userdebug_2306021732 【VIN】HRYTTESTVINMGM403			

History

- #1 - 2023-06-05 20:56 - CD TEST-方永红
- ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/118556
- #2 - 2023-06-06 10:15 - CD APP-王营
- Status changed from New to ASSIGNED
 - Assignee changed from CD APP-王营 to CD APP-王宏
- to 王宏
- 确认此问题是否是三方应用自身问题
- #3 - 2023-06-06 13:50 - CD APP-王宏
- Status changed from ASSIGNED to NEED_INFO

- Assignee changed from CD APP-王宏 to CD TEST-方永红

■ Current conclusion

分析完毕

■ My analysis

根据视频所示，华为应用市场的设计是 连续返回两次退出应用，而视频中操作不连贯，导致无法返回。

■ Next action

正常情况，申请关闭

#4 - 2023-06-17 18:58 - CDTS_TEST 王成

- Status changed from NEED_INFO to RESOLVED

客户自己操作问题

#5 - 2023-06-17 18:59 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

#6 - 2023-06-17 18:59 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED