

Status:	CLOSED	Start date:	2023-06-08
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】EE环境 【问题出现时间】：20230606 19点55分（第266次开机） 【前提条件】：车机上电（KL30ON，KL15 ON，已连接中控和功放，可正常输出声音） 1.副屏KL15下电再上电，查看开机时间 【实际结果】 副屏开机第一阶段约为8s，第二阶段约为15s（副屏0100版本第一阶段时间约为4s，第二阶段约为15s），开机时长变长 【期望结果】 副屏开机时间优化，第一阶段时长不比0100版本长. 【备注】： 车架号VIN：HRYTTESTVINMGM400附件为副屏的log 【影响版本】：副屏：01.00.0106.c104 中控：03.02.0088.C103 【硬件版本号】：/ 【是否能恢复】：			

History

- #1 - 2023-06-10 18:37 - CD TPM-王祥林
- Status changed from New to RESOLVED
- Assignee changed from CD TPM-王祥林 to CD TEST-方永红

转到jira上跟踪，内部票关闭。

- #2 - 2023-07-03 15:26 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

- #3 - 2023-07-03 15:26 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files

19点55分开机时长变长.mp4	9.06 MB	2023-06-08	CD TEST-方永红
19点55分开机第一阶段时间变长.7z	187 KB	2023-06-08	CD TEST-方永红