

Figure - Bug #118640
IOVDEV-33232 【内部】 【VC1】 【0106】 【台架】 【EE环境】 【副屏】 【设置】 控制中心互联网显示以太网后面带个句号

2023-06-08 15:16 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-08
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	0106
Need_Info:	--	Degrated:	--
Resolution:	INVALID	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	AOSP 原生如此
Test Type:	ST		
Description			
环境信息】EE环境 【问题出现时间】：20230607 16：11 【前提条件】：副屏上电，中控已连接 【操作步骤】 1.主界面下滑手势进入控制中心 【实际结果】 1.控制中心互联网显示以太网后面带个句号 【期望结果】 1.控制中心互联网显示以太网后面没有句号 【备注】： 【当前开机次数】：161 【应用版本】： 【硬件版本号】： 【VIN】HRYTTESTVINMGM401 【中控版本号】：03.02.0088.C103 【副屏版本号】：01.00.0106（01.00.0104）			

History

- #1 - 2023-06-08 17:38 - CD FW-廖涛
- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛
- #2 - 2023-06-08 19:33 - CD FW-廖涛
- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- Root cause set to AOSP 原生如此

■ Current conclusion
AOSP 原生文案，没有定制需求，不做处理。

■ Next action

测试确认并同步客户。

#3 - 2023-06-09 13:59 - CD TEST-方永红

- Status changed from *NEED_INFO* to *RESOLVED*
- Resolution changed from -- to *INVALID*

#4 - 2023-06-09 13:59 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*

#5 - 2023-06-09 13:59 - CD TEST-方永红

- Status changed from *VERIFIED* to *CLOSED*