

Status:	CLOSED	Start date:	2023-06-09
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-10
Test Type:	ST	Root cause:	编码问题
Description			
【环境信息】：EE环境 【问题出现时间】：20230608 17:13，第226次开机 【前提条件】：长按桌面2S进入编辑状态 【操作步骤】：勾选系统应用+第三方应用，卸载 【实际结果】：卸载完第三方应用后卸载按钮未置灰 【期望结果】：成功卸载第三方应用，“卸载”按钮置灰显示 【备注】：https://ofs.human-horizons.com/#/download/index/UrqMIUm%2BSI8%3D 【副屏版本号】：01.00.0106.C104 【中控版本号】：03.02.0088.C103.02_userdebug_2306021732 【VIN】HRYTTESTVINMGM403			

History

#1 - 2023-06-09 15:51 - CD APP-王营

- Status changed from New to ASSIGNED

- Assignee changed from CD APP-王营 to CD APP-王宏

#2 - 2023-06-09 16:55 - CD APP-王宏

- % Done changed from 0 to 50

- Root cause set to 编码问题

■ Current conclusion

已提交

■ My analysis

逻辑问题，未判断选中应用中是否存在可卸载的应用（非系统应用）

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+206027>

#3 - 2023-06-09 17:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
206027	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

AF:Launcher:Uninstall button should gray when donot has third part appTC-RID: 0301-0205304IssueID: TS-R-BUG-118716Change-Id: I34a37dfcb70ba79d5cf48055d87f40a4a917aa23

#4 - 2023-06-09 17:33 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-06-10

#5 - 2023-06-12 13:53 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在 FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306100050 版本验证通过

#6 - 2023-06-25 13:58 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED