

Status:	CLOSED	Start date:	2023-06-17
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	110 (6/16) 合入荔枝播客版本
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	2023-06-26
Test Type:	Release Test	Root cause:	微服务消息发送时序问题
Description			
前置条件： 1.设备连接中控，网络正常 2.在中控执行 adb root adb shell ssh root@223.255.255.1 dbus-send --bus=tcp:host=223.255.255.1,port=55666 --type=signal / ipcl.out.to.droid.SWC2VHAL_COMM array:byte:3,51,1 【测试步骤】 中控进入设置-显示-息屏模式，频繁点击“仅副驾屏” 【预期结果】 屏幕状态显示正确 【测试结果】 副屏应该亮屏，但屏幕没有亮是息屏状态			

History			
#1 - 2023-06-17 16:23 - CD FW 曹覃刚			
- Status changed from New to ASSIGNED			
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛			
#2 - 2023-06-25 20:52 - CD FW-廖涛			
■ Current conclusion			
1. 微服务消息发送时序问题；			
2. 中控息屏“仅副驾屏”高亮状态问题；			
问题1已经处理，问题2需要中控确认，已联系；			
■ Next action			
联系中控开发确认高亮状态；			
#3 - 2023-06-26 18:56 - IoT scm			
Gerrit Merge Information：			
ID	Project	Branch	Uploader
209490	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	tao.liao@thundersoft.com
	m/apps/MircoService	-dev	

AF:MicroService: Fixed send message timing confusion.TC-RID: 1201-0206101IssueID: TS-R-BUG-118828Change-Id: If7fe09795736e6d5eb89b6dc5aff1960d78ab2e6

- #4 - 2023-06-26 18:59 - CD FW-廖涛
- Status changed from ASSIGNED to RESOLVED
 - Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 唐霞
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-06-26
 - Root cause set to 微服务消息发送时序问题

■ Current conclusion

已处理，代码已入库。

■ My analysis

微服务消息发送时序问题，微服务消息发送已处理为同一 DestService 按照顺序发送。

■ Next action

测试验证。

#5 - 2023-06-26 20:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209948	general/platform/vendor/thundercom/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Fixed send message timing confusion.TC-RID: 1201-0206101IssueID: TS-R-BUG-118828Change-Id: If7fe09795736e6d5eb89b6dc5aff1960d78ab2e6(cherry picked from commit e56874bdde668372712cd6542460fdaab1e37774)			

#6 - 2023-06-27 17:34 - 物联网测试组_CDTS 唐霞

验证100次未复现
验证版本114release (627)

#7 - 2023-07-05 17:18 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

验证通过关闭问题单
验证版本 : release119 (704)

#8 - 2023-07-05 17:18 - 物联网测试组_CDTS 唐霞

- Status changed from VERIFIED to CLOSED

Files

106-110.txt	9.14 MB	2023-06-17	物联网测试组_CDTS 唐霞
-------------	---------	------------	----------------