

Figure - Bug #118843

测试 Test-ST # 111337 (New): ST测试总票

测试 Test-ST # 116840 (New): 中控联调测试-AF

【AF】【EVT3】【音量调节】连接蓝牙耳机，调节副屏音量，中控副屏音量也被调节

2023-06-19 17:56 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-19
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	110 (616)
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	0115
Reproducibility:	Frequently	Fixed Version:	
Test Type:	ST	Root cause:	修复蓝牙连接后的状态问题
Description			
【测试版本】 110 (616版)			
【测试现象】 连接蓝牙耳机，调节副屏音量，中控副屏音量也被调节			

History

#1 - 2023-06-26 15:20 - Multimedia组-RD3_TSCD 梁卿山

Hi ALL

从当前日志来看，
此时蓝牙的状态属于断开状态，所以会调节到中控的音量。

```
175972:06-19 14:18:06.157 1534 7709 D AS.AudioService: idcm_af:a2dp bluetooth state= 2
175973:06-19 14:18:06.157 1534 7709 D AudioIDCMicroNegotiator: idcm_af:AudioIDCMicroNegotiator setBluetoothConnected: false
175975:06-19 14:18:06.157 1534 7709 D AS.AudioService: idcm_af:setBluetoothConnected: false
175976:06-19 14:18:06.157 1534 7709 D AS.AudioService: idcm_af:abandonAudioFocus, bluetooth is connected.
175978:06-19 14:18:06.157 1534 7709 D AudioIDCMicroNegotiator: idcm_af:abandonIDCMicroAudioFocus FocusState0
176087:06-19 14:18:06.162 1534 2443 D AS.AudioService: idcm_af:a2dp bluetooth state= 2
176088:06-19 14:18:06.162 1534 2443 D AudioIDCMicroNegotiator: idcm_af:AudioIDCMicroNegotiator setBluetoothConnected: false
176089:06-19 14:18:06.162 1534 2443 D AS.AudioService: idcm_af:setBluetoothConnected: false
176090:06-19 14:18:06.162 1534 2443 D AS.AudioService: idcm_af:abandonAudioFocus, bluetooth is connected.
176091:06-19 14:18:06.162 1534 2443 D AudioIDCMicroNegotiator: idcm_af:abandonIDCMicroAudioFocus FocusState0
178756:06-19 14:18:06.460 1534 2057 W AS.AudioService: idcm_warn: index is the same as old one, return
179831:06-19 14:18:10.839 1534 2057 D AS.AudioService: idcm_af:a2dp bluetooth state= 0
179832:06-19 14:18:10.839 1534 2057 D AudioIDCMicroNegotiator: idcm_af:AudioIDCMicroNegotiator setBluetoothConnected: false
179834:06-19 14:18:10.839 1534 2057 D AS.AudioService: idcm_af:setBluetoothConnected: false
180024:06-19 14:18:10.859 1534 1838 D AS.AudioService: idcm_volume:syncIDCMicroAudioVolume bluetooth disconnected
```

下一步：
查看蓝牙的状态为什么不对。

#2 - 2023-06-26 16:30 - Multimedia组-RD3_TSCD 梁卿山

Hi ALL

根据当前分析，是因为在蓝牙广播时，我们未将状态完整的修改，导致了蓝牙状态有问题。

下一步：
当前已经有方案进行修复。

#3 - 2023-06-27 15:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210367	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix Bluetooth status issuesFix Bluetooth status issuesTC-RID: 0301-0900116IssueID: TS-R-DF-118843Change-Id: I17f0e39a88d727df5602c6cfc483c228200e605d			

#4 - 2023-06-27 15:16 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from New to RESOLVED
- Assignee changed from Multimedia组-RD3_TSCD 梁卿山 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Root cause set to 修复 蓝牙连接后的状态问题

Hi 永红

该问题已经合入patch修复，请使用6月27日后版本验证，谢谢！

#5 - 2023-06-27 21:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210445	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix Bluetooth status issuesFix Bluetooth status issuesTC-RID: 0301-0900116IssueID: TS-R-DF-118843Change-Id: I17f0e39a88d727df5602c6cfc483c228200e605d(cherry picked from commit ab2231c9b90ddb6170925707de3242ccd3ddf601)			

#6 - 2023-06-28 15:58 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to 0115

6.28
验证通过

#7 - 2023-06-28 15:58 - **CD TEST-方永红**
- Status changed from *VERIFIED* to *CLOSED*

Files			
fp.txt	23.6 MB	2023-06-19	CD TEST-方永红
tlog_sts40x190123_000251_0619161101.tar.gz	13.9 MB	2023-06-19	CD TEST-方永红
中科创达软件股份有限公司20230619-175540.mp4	16.8 MB	2023-06-19	CD TEST-方永红