

Status:	NEED_INFO	Start date:	2023-06-30
Priority:	High	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	TEST	Found Version:	0629-OTA-0630
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Rarely	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【测试步骤】 1、单副屏0629-OTA-0630 2、插入中控网线等 ->时间不同步、网络图标不同步、音量亮度调节不同步 3、断电重启 ->时间同步、wifi图标同步，但是副屏不显示“无服务” 4、断开网线 ->副屏出现“无服务” 5、插入网线 ->正常同步 日志已飞书提供			
Related issues:			
Related to Figure - Bug # 118950: 【AF】【EVT3】【中控联调】OTA升级后...		CLOSED	2023-06-30

History

#1 - 2023-07-04 20:52 - CD FW-廖涛

- Status changed from New to NEED_INFO

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- Need_Info changed from -- to TEST

■ My analysis

从第 431 次开机的日志分析，微服务没有与中控成功建立连接，副屏一直处于网络不通的状态，所以副屏的相关表现属于正常情况。由于没有现场，无法分析副屏网络不通的原因，需要复现后现场看副屏与中控的网络连通性。

06-30 10:11:46.645 2306 2624 E MicroService: DTC_ETH: BaseMicroSocketClient:createClientSocket()

06-30 10:11:46.645 2306 2624 E MicroService: java.net.NoRouteToHostException: Host unreachable

06-30 10:11:46.645 2306 2624 E MicroService: at libcore.io.IoBridge.connect(IoBridge.java:183)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.PlainSocketImpl.socketConnect(PlainSocketImpl.java:142)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.AbstractPlainSocketImpl.doConnect(AbstractPlainSocketImpl.java:390)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.AbstractPlainSocketImpl.connectToAddress(AbstractPlainSocketImpl.java:230)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.AbstractPlainSocketImpl.connect(AbstractPlainSocketImpl.java:212)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.SocksSocketImpl.connect(SocksSocketImpl.java:436)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.Socket.connect(Socket.java:621)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.Socket.connect(Socket.java:570)

06-30 10:11:46.645 2306 2624 E MicroService: at java.net.Socket.<init>(Socket.java:450)
06-30 10:11:46.645 2306 2624 E MicroService: at java.net.Socket.<init>(Socket.java:292)
06-30 10:11:46.645 2306 2624 E MicroService: at com.thundercomm.microservice.base.BaseMicroSocketClient.createClientSocket(BaseMicroSocketClient.java:20)
06-30 10:11:46.645 2306 2624 E MicroService: at com.thundercomm.microservice.MicroSocketClient.serialSendMessage(MicroSocketClient.java:100)
06-30 10:11:46.645 2306 2624 E MicroService: at
com.thundercomm.microservice.MicroSocketClient.lambda\$handShake\$1\$MicroSocketClient(MicroSocketClient.java:115)
06-30 10:11:46.645 2306 2624 E MicroService: at com.thundercomm.microservice.MicroSocketClient\$\$ExternalSyntheticLambda0.run(Unknown Source:4)
06-30 10:11:46.645 2306 2624 E MicroService: at java.lang.Thread.run(Thread.java:920)

■ Next action

需要复现后现场抓取相关日志数据进行分析。

#2 - 2023-07-17 16:18 - CDTS_TEST 王成
- Assignee changed from CD TEST- 方永红 to 移动测试一组_CDTS 刘强

#3 - 2023-07-18 14:28 - 移动测试一组_CDTS 刘强

Release版本 120
Release版本 122
未复现

#4 - 2023-07-20 17:35 - 移动测试一组_CDTS 刘强

DB_0720 手动验证10次未复现

#5 - 2023-08-02 15:58 - 移动测试一组_CDTS 刘强

0128 压测30次未复现