

Figure - Bug #118951

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110894 (New): AF-V1.0功能测试-屏保

【AF】【EVT】【屏保】OTA升级后出现，部分设备屏保资源未更新

2023-07-01 10:56 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-07-01
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	116版本
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-07-04
Test Type:	ST	Root cause:	编码问题
Description			
【前提条件】 设备已开机			
【测试步骤】 1、进入设置-显示-屏保 2、查看系统屏保 3、选择其中一个屏保应用			
【预期结果】 2、三台设备都更新了资源 3、设置屏保为正常新资源			
【实际结果】 2、三台设备中两台未更新屏保资源 3、未更新资源设备显示为车			
【备注】 三台中其中一台设备系统屏保显示为车，应用第一个屏保显示为车，应用第二个屏保显示为新资源图片			

History

- #1 - 2023-07-03 11:34 - CD APP-王宏
- Status changed from New to NEED_INFO
- Assignee changed from CD APP-王宏 to CDTs_Test 吴诗雨

■ Current conclusion

分析中

■ My analysis

初步判定为图片缓存,另外根据 覃刚 所说，该版本以前的还未装车，用户拿到的肯定是最新的版本，我们这边不需要做调整

■ Next action

麻烦刷一个最新的版本，不要通过OTA升级，检查屏保是否展示正常，确认正常后还请关闭

#2 - 2023-07-03 14:35 - CDTs_Test 吴诗雨

- Assignee changed from CDTs_Test 吴诗雨 to CD TPM- 王祥林

经确认，从低版本Q刷上来也是同样的情况，系统屏保图片未更新，应用后与图片不符，恢复出厂设置后正常。

请判断是否需要针对OTA升级后的情况进行处理

#3 - 2023-07-03 14:46 - CD TPM-王祥林

- Status changed from NEED_INFO to ASSIGNED

- Assignee changed from CD TPM- 王祥林 to CD APP- 王宏

王宏

需要处理一下，虽然最终用户拿到的新车不会有问题。但之前出去了测试车，展车，试驾车这些都是旧版本，还是要保证这些车升到新版本后没有问题。

#4 - 2023-07-03 18:12 - CD APP-王宏

- % Done changed from 0 to 50

■ Current conclusion

已提交

■ My analysis

根据现象判断是图片加载框架的缓存问题，

其次，在屏保展示页检查该图片是否存在，不存在则加载默认屏保(确保更换图片后不展示原先的屏保图片)

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+211939>

#5 - 2023-07-03 19:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211939	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:ScreenSaver:Fixed pic cache issueTC-RID: 1201-0300603IssueID: TS-R-BUG-118951Change-Id: Ifed14af400da54db31d123074c042dd7e6e2a4f8			

#6 - 2023-07-03 19:54 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD APP- 王宏 to CDTs_Test 吴诗雨

- % Done changed from 50 to 100

- Resolution changed from -- to FIXED

- Fixed Version set to 2023-07-04

- Root cause set to 编码问题

#7 - 2023-07-04 15:30 - CDTs_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

刷机112版本，恢复出厂设置后，ota升级为0704DB，设备屏保更新，验证通过。

#8 - 2023-07-04 15:31 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

#9 - 2023-07-04 15:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212126	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:Fixed pic cache issueTC-RID: 1201-0300603IssueID: TS-R-BUG-118951Change-Id: Ifed14af400da54db31d123074c042dd7e6e2a4f8(cherry picked from commit b165dfdb054401fc92b40779d979ae66dbf0f61e)			

#10 - 2023-07-05 16:34 - CDTS_Test 吴诗雨

119版本，验证通过

Files

20230701-105557.mp4	3.19 MB	2023-07-01	CDTS_Test 吴诗雨
---------------------	---------	------------	---------------