

Status:	CLOSED	Start date:	2023-07-01
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	0%
Category:	冻屏	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	116版本
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	
Test Type:	Release Test	Root cause:	屏端更新了新固件导致的
Description			
【问题描述】 概率出现，断电重启后TP不可用			

History

- #1 - 2023-07-03 19:47 - CD TPM-王祥林
- Status changed from New to RESOLVED
  - Assignee changed from CD TPM-王祥林 to 物联网测试组\_CDTS 唐霞
  - Found Version changed from 116热了版本 to 116版本
  - Root cause set to 屏端更新了新固件导致的

已回退屏端固件解决此问题，在117版本验证。  
<https://dev.thundercomm.com/gerrit/c/general/vendor/thundercomm/products/figure/+/211902>

#2 - 2023-07-05 17:10 - 物联网测试组\_CDTS 唐霞

117版本验证50次未复现。屏端问题关闭问题单

#3 - 2023-07-05 17:10 - 物联网测试组\_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

#4 - 2023-07-05 17:10 - 物联网测试组\_CDTS 唐霞

- Status changed from VERIFIED to CLOSED