

Status:	ASSIGNED	Start date:	2023-07-04
Priority:	Normal	Due date:	
Assignee:	Multimedia组-RD3_TSCD 梁卿山	% Done:	0%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0118
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	0136
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】 台架			
【前提条件】 1.设备正常上电 2.设备已安装QQ			
【操作步骤】 1.副屏接到QQ语音来电处于通话中 2.副屏连上蓝牙耳机或蓝牙音箱 3.副屏连上蓝牙音箱或蓝牙耳机			
【实际结果】 语音通话没有声音输出，mic正常			
【期望结果】 语音通话从最后连上的蓝牙设备输出声音			
时间：2023.7.4 10:42			

History

#1 - 2023-08-01 16:44 - Multimedia组-RD3_TSCD 梁卿山

当前结论

从上述日志和qxdm数据来看,audio侧没有发现异常.我们将尝试复现此问题继续确认.

当前分析

从上述13.txt来看,设备正常开启

07-04 10:38:38.762 822 1034 D audio_hw_primary: enable_snd_device: snd_device(43: bt-sco-headset-wb) **开启bt听筒

07-04 10:38:38.762 822 1034 D audio_hw_utils: audio_extn_utils_send_app_type_cfg: usecase->out_snd_device bt-sco-headset-wb

07-04 10:38:38.762 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(43) num devices(0) new_snd_devices(0)

07-04 10:38:38.763 822 1034 I audio_hw_utils: send_app_type_cfg_for_device PLAYBACK app_type 69946, acdb_dev_id 39, sample_rate 16000, snd_device_be_idx 32

07-04 10:38:38.763 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(43) num devices(1) new_snd_devices(0)

07-04 10:38:38.763 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(43) num devices(0) new_snd_devices(0)

07-04 10:38:38.798 822 1034 D audio_hw_primary: disable_snd_device: snd_device(177: bt-sco-mic-wb)

07-04 10:38:38.798 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(177) num devices(0) new_snd_devices(0)

07-04 10:38:38.798 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(177) num devices(0) new_snd_devices(0)

07-04 10:38:38.798 822 1034 D audio_hw_primary: enable_snd_device: snd_device(177: bt-sco-mic-wb) **开启bt麦克

07-04 10:38:38.798 822 1034 D msm8974_platform: platform_get_island_cfg_on_device:island cfg status on snd_device = (bt-sco-mic-wb 0)
07-04 10:38:38.800 822 1034 D audio_hw_utils: audio_extn_utils_send_app_type_cfg: usecase->in_snd_device bt-sco-mic-wb
07-04 10:38:38.800 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(177) num devices(0) new_snd_devices(0)
07-04 10:38:38.800 822 1034 I audio_hw_utils: send_app_type_cfg_for_device CAPTURE app_type 69946, acdb_dev_id 38, sample_rate 16000, snd_device_be_idx 33
07-04 10:38:38.800 822 1034 D msm8974_platform: platform_split_snd_device: snd_device(177) num devices(1) new_snd_devices(0)
07-04 10:38:38.831 822 1034 D audio_hw_primary: adev_set_parameters: enter: BT_SCO=on
07-04 10:38:38.833 1621 1965 I AS.AudioDeviceInventory: setPreferredDevicesForStrategySync, strategy: 15 devices: [AudioDeviceAttributes: role:output type:bt_sco
addr:00:00:00:00:00:00]

从上述tlog中的qxdm数据来看.1586和152e节点能够清晰的听到对方说话的声音.

所以目前没有发现audio侧存在异常.

下一步

我们将尝试u复现继续确认此现象.

#2 - 2023-08-02 11:22 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from New to NEED_INFO
- Assignee changed from Multimedia组-RD3_TSCD 梁卿山 to 物联网测试组_TSCD 王维

Hi 王维

麻烦帮忙复现一下该问题，看最新版还是否存在该问题，而且获取一下QXDM日志。

#3 - 2023-08-23 16:10 - 物联网测试组_TSCD 王维

- File wusheng.txt added
- Assignee changed from 物联网测试组_TSCD 王维 to Multimedia组-RD3_TSCD 梁卿山
- Verified Version set to 0136

该现象在0136版本复现；
复现时间：20230823 16:05和16:02
QXDM日志：ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_118413/118969/tlog_iov0201017500006162025411a2212290000001371_012899_0823160521.tar.gz

#4 - 2023-08-24 15:52 - CDTs_TEST 王成

- Status changed from NEED_INFO to ASSIGNED

Files			
13.txt	25.5 MB	2023-07-04	物联网测试组_TSCD 王维
tlog_iov0201017500006162025411a2305070000003741_000075_0704104338.tar.g	23.1 MB	2023-07-04	物联网测试组_TSCD 王维
wusheng.txt	10.9 MB	2023-08-23	物联网测试组_TSCD 王维