

Figure - Bug #119006

测试 Test-ST # 113421 (New): V4.0功能与专项测试

测试 Test-ST # 113423 (New): V4.0专项--BSP专项--稳定性-各项功能长时间运行

【AF】【EVT】【稳定性】MTBF任务管理器打开小窗应用长时间跑测，出现多次任务管理器中小窗卡片与全屏卡片重叠的情况

2023-07-10 10:15 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-07-10
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	0706DB
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-07-22
Reproducibility:	Frequently	Root cause:	编码问题
Test Type:	ST		
Description			
【前提条件】			
1、设备成功启动			
2、确保MTBF脚本运行的前置条件已准备			
【测试步骤】			
1、使用python运行对应MTBF脚本			
2、运行四天			
3、查看设备运行结果			
【预期结果】			
3、设备正常运行			
【实际结果】			
3、出现多次任务管理器中小窗卡片与全屏卡片重叠的情况			
【mtbf模块步骤】			
1、打开任务管理器			
2、随机点击小窗窗口的任一应用			
3、重复以上步骤			

History

#1 - 2023-07-10 10:30 - CDTS_Test 吴诗雨

- Description updated

#2 - 2023-07-18 11:10 - CD APP-王宏

- % Done changed from 0 to 50

- Root cause set to 编码问题

■ Current conclusion

已提交

■ My analysis

卡片数量正确，说明在初始化卡片的时候是能正确获取到小窗状态的，因此，在初始化位置处再次计算小窗的位置，确保小窗缩略图不会和卡片重叠在一起

■ Submit URL
<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Launcher3/+/215614>

#3 - 2023-07-18 17:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215614	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006Change-Id: If9f0654d1f425aa7204c23ae1c4891dd58cb5367			

- #4 - 2023-07-18 17:15 - CD APP-王宏
- Status changed from New to RESOLVED
 - Assignee changed from CD APP-王宏 to CDTS_Test 吴诗雨
 - % Done changed from 50 to 100
 - Resolution changed from -- to FIXED
 - Fixed Version set to 2023-07-19

#5 - 2023-07-20 00:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216249	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006Change-Id: If9f0654d1f425aa7204c23ae1c4891dd58cb5367(cherry picked from commit 1b2ccfec345255fa7a63700e700b86efc0690d19)			

- #6 - 2023-07-20 10:21 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to ASSIGNED
 - Assignee changed from CDTS_Test 吴诗雨 to CD APP-王宏

0719DB，验证失败

#7 - 2023-07-20 18:08 - CD APP-王宏

- Current conclusion
- 已提交
- My analysis
- 1.设置卡片位置的代码（依赖步骤2）
 - 2.小窗渲染时设置小窗状态

用户操作执行顺序是 1 2

脚本操作执行顺序是 2 1
导致未获取到正确的小窗状态

解决方案是实时获取小窗状态，不依赖小窗渲染时机

■ Submit URL
<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+216308>
<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+216426>

#8 - 2023-07-21 13:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216426	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006Change-Id: I6863d09851d1c87ed4080e016200a9ff103f589e			

#9 - 2023-07-21 13:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216308	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
Revert AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006This reverts commit 1b2ccfec345255fa7a63700e700b86efc0690d19.Reason for revert: <not fixed>Change-Id: I2c3545a619ad9bb1c63010198ed0ae128ae47e9e			

#10 - 2023-07-21 13:41 - CD APP-王宏
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CDTS_Test 吴诗雨
- Fixed Version changed from 2023-07-19 to 2023-07-22

#11 - 2023-07-25 09:40 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

#12 - 2023-07-25 10:17 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

0722DB验证通过

#13 - 2023-07-27 23:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

218258	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006Change-Id: I6863d09851d1c87ed4080e016200a9ff103f589e(cherry picked from commit 8c2ccef7ae208442d7692bfab4c8bc6a3b284acd)			

#14 - 2023-07-27 23:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218259	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert AF:Launcher:Solve the overlapping of small windows and RecentsTC-RID: 1201-0205302IssueID: TS-R-BUG-119006This reverts commit 1b2ccfec345255fa7a63700e700b86efc0690d19.Reason for revert: <not fixed>Change-Id: I2c3545a619ad9bb1c63010198ed0ae128ae47e9e(cherry picked from commit 6299e1ca78c2d2bba0c1d62ec35ec8f0b8e4da1c)			

Files

2023-07-06-17-41-05.jpg	116 KB	2023-07-10	CDTS_Test 吴诗雨
-------------------------	--------	------------	---------------