

Status:	CLOSED	Start date:	2023-07-24
Priority:	Normal	Due date:	
Assignee:	物联网测试组_TSCD 王维	% Done:	0%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0722DB
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【前提条件】 1.设备网络正常 2.已下微信、企业微信、QQ等基础viop应用 【操作步骤】 1.使用企业微信拨打语音电话 2.使用微信拨打语音电话 3.使用QQ拨打语音电话 4.重复步骤1和2 【实际结果】 1和2没有声音输出 3声音输出正常 4声音输出正常 【预期结果】 语音和视频声音输出均正常 【备注】 版本变更：从7.24音频VB qfil 到7.22DB			

History
#1 - 2023-07-24 16:11 - 物联网测试组_TSCD 王维
使用飞书拨打语音该现象必现
#2 - 2023-07-25 10:30 - Multimedia组-RD3_TSCD 梁卿山
Hi ALL
1.飞书问题已经另外起票对应
2.微信和企业微信的问题；
当前分析：
在开启通话时，setmode比start_output_stream慢了，导致usecase使用的是low-latency-playback，不是电话通道，导致了该问题；

58204:07-24 15:18:10.116 1000 1243 D APM_AudioPolicyManager: startOutput() output 13, stream 0, session 81

58219:07-24 15:18:10.117 814 14684 D audio_hw_primary: start_output_stream: enter: stream(0xebf821a0)usecase(1: low-latency-playback) devices(0x2) is_haptic_usecase(0)

58432:07-24 15:18:10.151 814 866 D audio_hw_primary: adev_set_mode: mode 3 , prev_mode 0

58462:07-24 15:18:10.189 814 14580 D audio_hw_primary: select_devices for use case (low-latency-playback)

下一步：

该问题仅在刷机完复现，重启后就正常，当前进一步对比查看区别在哪。

#3 - 2023-07-26 11:30 - Multimedia组-RD3_TSCD 梁卿山

Hi ALL

当前现状：

1.当前方案存在问题，重新优化后编译VB中。

下一步：

等待VB验证。

#4 - 2023-07-27 16:00 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from New to ASSIGNED

Hi ALL

当前分析：

该问题是之前的两个patch投入导致，将会回退相关ptach。

#5 - 2023-07-27 17:02 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
218121	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM: Audio: Revert MM: Audio: disable voip_rxRevert MM: Audio: Fix some voiceless issues with VOIP appRevert MM: Audio: disable voip_rxTC-RID: 0301-0900116IssueID: TS-R-DF-119086Change-Id: I29017ba919f88d845aa915832025ae31448bb197			

#6 - 2023-07-27 20:14 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader

218248	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Revert MM: Audio: disable voip_rxRevert MM: Audio: Fix some voiceless issues with VOIP appRevert MM: Audio: disable voip_rxTC-RID: 0301-0900116IssueID: TS-R-DF-119086Change-Id: I29017ba919f88d845aa915832025ae31448bb197(cherry picked from commit 00bead6210940ed6c6ceced8eb1fd5e1b07a9733)			

#7 - 2023-07-28 16:51 - CD TEST-方永红

【测试版本】0127
【测试情况】未复现微信和企业微信不出声的问题

#8 - 2023-08-01 16:48 - Multimedia组-RD3_TSCD 梁卿山
- Assignee changed from Multimedia组-RD3_TSCD 梁卿山 to CD TEST-方永红

麻烦监视三个版本,三个版本不复现麻烦关票.

#9 - 2023-08-31 16:22 - CDTS_TEST 王成
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD TEST-方永红 to 物联网测试组_TSCD 王维

#10 - 2023-10-08 09:56 - 物联网测试组_TSCD 王维
- Status changed from RESOLVED to VERIFIED

已在0136之后连续跟踪3个版本未复现，关闭

#11 - 2023-10-08 09:57 - 物联网测试组_TSCD 王维
- Status changed from VERIFIED to CLOSED

Files			
wushengyin.txt	10.5 MB	2023-07-24	物联网测试组_TSCD 王维