

Figure - Bug #119106

【BSP】【EVT3】【Tlog】Tlog勾选实时日志后，KL15重启或OTA升级后，再次进入tlog选择历史，点击start之后抓出来的是实时日志

2023-07-28 15:02 - 移动测试一组_CDTs 刘强

Status:	CLOSED	Start date:	2023-07-28
Priority:	High	Due date:	
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	SYSTEM	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0127
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-08-02
Test Type:	ST	Root cause:	apk逻辑代码问题
Description			
【前提条件】 None			
【测试步骤】 1. 烧写127版本 2. *#147#勾选实时日志，并点击start 3. KL15或OTA升级 4. 重新进入tlog，选择历史日志点击start			
【预期结果】 4 tlog正常抓取历史日志			
【实际结果】 4 tlog抓出来的是实时日志			

History

#1 - 2023-08-01 20:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219184	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM :Tlog: Solving the apk problem of tlog(3)modify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID: TS-R-BUG-119106Change-Id: I2a38ec47d6f782e7a35d17728d74693f2fd2212f			

#2 - 2023-08-02 09:53 - CD SYSTEM-夏旭

- Status changed from New to RESOLVED
- Assignee changed from CD SYSTEM-夏旭 to 移动测试一组_CDTs 刘强
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2023-08-02
- Root cause set to apk逻辑代码问题

【目前进展】

在选择实时日志并且抓取之后，logtype的值就是manual
因为逻辑问题，下一次进入时自动选择了历史日志，但是logtype却是manual
在onresume的时候判断logtype的值，如果是manual就选中manual，不用再去判断是否正在抓取日志

【下一步计划】

相关代码已经入库，麻烦用最新的DB验证

#3 - 2023-08-03 17:56 - 移动测试一组_CDTs 刘强
- Status changed from RESOLVED to VERIFIED

验证版本：DB_0803
验证结果：验证通过
验证方法：
1. 点击实时日志，返回桌面，再次进入tlog，抓取历史日志正常
2. 点击实时日志，KL15重启，再次进入tlog，抓取历史日志正常
3. 点击实时日志，OTA升级重启，再次进入tlog，抓取历史日志正常
4. 历史日志、实时日志切换抓取正常

#4 - 2023-08-03 17:56 - 移动测试一组_CDTs 刘强
- Status changed from VERIFIED to CLOSED

#5 - 2023-08-04 10:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300124	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
SYSTEM :Tlog: Solving the apk problem of tlog(3)modify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID: TS-R-BUG-119106Change-Id: I2a38ec47d6f782e7a35d17728d74693f2fd2212f(cherry picked from commit a321a59cb84d22080851ea3c088a4b5076622a70)			

Files			
all1.txt	2.5 MB	2023-07-28	移动测试一组_CDTs 刘强
tlog_iov0201017500006162025411a2305070000003681_003312_0728143455.tar.gz	1.9 MB	2023-07-28	移动测试一组_CDTs 刘强