

Figure - 需求 Requirement #119113
[DNS]根据中控的不同网络动态设置DNS

2023-07-29 14:42 - CD LC邓帅

Status:	分析&分解中 In Analysis	Start date:	2023-07-29
Priority:	Normal	Due date:	2023-08-04
Assignee:	CD LC邓帅	% Done:	60%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
1.当中控使用tbox(5G)上网时，设置副屏DNS为218.4.4.4。 2.当中控使用Wi-Fi上网时，设置副屏DNS为中控发送的值。			

History

#1 - 2023-07-29 14:43 - CD LC邓帅

- % Done changed from 0 to 60

Update progress:
修改已经提交到Gerrit，正在VB验证。
https://dev.thundercomm.com/gerrit/q/topic:FIGURE_MK_MICROSETTINGS_DNS

#2 - 2023-08-01 21:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216963	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:DNS: Set DNS according to WiFi/Tbox usedAccording to the network(WiFi/Tbox) used, set the different DNS.TC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: Iff411416dae5d9ac1c3a9856b12a3ad3f63fce4			

#3 - 2023-08-01 21:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216975	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:DNS: Change the default DNS server to 218.4.4.4Chagne the default DNS server from 101.226.4.6 to 218.4.4.4TC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: I4058706d7961aede3edef7edb08bb012df435a57			

#4 - 2023-08-01 21:44 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
216986	general/platform/frameworks/opt/net/ethernet	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:Ethernet: Ignore the saving configTC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: I10e15d86775e2ce21d9279ed48dc52593ea5a37d			

#5 - 2023-08-01 22:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218576	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:Network: Handling pointer exceptionsIf the destination is , do not set the gateway address.TC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: I8df8087e9e00a3cdd91ba5641b79686d2c384978			

#6 - 2023-08-10 20:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302369	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:DNS: Set DNS according to WiFi/Tbox usedAccording to the network(WiFi/Tbox) used, set the different DNS.TC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: Iff411416dae5d9ac1c3a9856b12a3ad3f63fcca4(cherry picked from commit 82f1279d8972054afe30523ef99c98d3a7ed5aa)			

#7 - 2023-08-10 20:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302370	general/platform/frameworks/opt/net/ethernet	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Ethernet: Ignore the saving configTC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: I10e15d86775e2ce21d9279ed48dc52593ea5a37d(cherry picked from commit 0d5525dca7af6a966703e775df372374af9a476c)			

#8 - 2023-08-10 20:37 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
302371	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Network: Handling pointer exceptionsIf the destination is , do not set the gateway address.TC-RID: 1201-0400601IssueID: TS-R-DF-119113, IOVDEV-37689Change-Id: I8df8087e9e00a3cdd91ba5641b79686d2c384978(cherry picked from commit 3038f4c0324de0d18adeaa6470ce50f4844266c8)			

#9 - 2023-11-06 19:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318332	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xin.yang_a@thundersoft.com
LC:Ethernet:Strengthen routing settingsStrengthen routing settingsTC-RID: 0301-0201802IssueID: TS-R-DF-119113, FIR-776Change-Id: I6a7bc91a70542cb0515b71d98e3357d20a56e099			

#10 - 2023-11-08 22:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326551	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Ethernet:Strengthen routing settingsStrengthen routing settingsTC-RID: 0301-0201802IssueID: TS-R-DF-119113, FIR-776Change-Id: I6a7bc91a70542cb0515b71d98e3357d20a56e099(cherry picked from commit 1c1f07852a04c0f802c74e8de8b3023c37580b5b)			

#11 - 2023-11-14 10:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327750	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert LC:Ethernet:Strengthen routing settingsThis reverts commit 4b96bda21aa0be70b27acdb4fce6655126ebe627.Reason for revert: <no network>TC-RID: 0301-0201802IssueID: TS-R-DF-119113, FIR-776Change-Id: Ib2eec7ce989f2e8cc8f07e4b81dbfd253cec9fcd			

#12 - 2023-11-14 10:51 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
327873	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
Revert LC:Ethernet:Strengthen routing settingsThis reverts commit 1c1f07852a04c0f802c74e8de8b3023c37580b5b.Reason for revert: <fix no network>TC-RID: 0301-0201802IssueID: TS-R-DF-119113, FIR-776Change-Id: I2bb43358b3d8104d5516e91dc7968bb7ac1290a6			

#13 - 2023-11-17 13:52 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
327372	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:Network: Modify the VLAN interface of the mapping tbxModify the VLAN interface of the mapping central controller tbx.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I3937fc650f0c7cd0e54db70338711f2f33917d85			

#14 - 2023-11-17 14:41 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
328716	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Network: Modify the VLAN interface of the mapping tbxModify the VLAN interface of the mapping central controller tbx.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I3937fc650f0c7cd0e54db70338711f2f33917d85(cherry picked from commit 770c1e904f5eca148cb8f1c87f7935956aca29ca)			

#15 - 2023-11-20 17:47 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
329523	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp_0146	wangxl0510@thundersoft.com
LC:Network: Modify the VLAN interface of the mapping tbxModify the VLAN interface of the mapping central controller tbx.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I3937fc650f0c7cd0e54db70338711f2f33917d85(cherry picked from commit 770c1e904f5eca148cb8f1c87f7935956aca29ca)			

#16 - 2023-12-04 23:44 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
333422	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev_vx1	wangxl0510@thundersoft.com
Revert LC:Network: Modify the VLAN interface of the mapping tboxThis reverts commit 770c1e904f5eca148cb8f1c87f7935956aca29ca.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I589f1273692f1b09a7069c0ebe9016b8fc517627			

#17 - 2023-12-04 23:48 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
333364	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp_vx1	wangxl0510@thundersoft.com
Revert LC:Network: Modify the VLAN interface of the mapping tboxThis reverts commit 770c1e904f5eca148cb8f1c87f7935956aca29ca.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I589f1273692f1b09a7069c0ebe9016b8fc517627(cherry picked from commit 2f10b443b11eff727c27fc9141c56a38fec9c6e0)			

#18 - 2023-12-27 14:41 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
332794	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptable rules.Only 192.168.4.16 can use 2020 port.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I90fe3bccd62b4da14b3e8f5e5f10c0ee7cc0f14b			

#19 - 2023-12-27 14:41 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
332795	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptables sepolicy.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id:			

#20 - 2023-12-28 15:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340721	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptable rules.Only 192.168.4.16 can use 2020 port.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I90fe3bccd62b4da14b3e8f5e5f10c0ee7cc0f14b(cherry picked from commit 35ab9e507adf9b58ecd85cdc13915cc83fe7a158)			

#21 - 2023-12-28 15:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340722	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptables sepolicy.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: Ia0bc6de5d257964cfe634b27c9815d7d63ec08a9(cherry picked from commit bbfb24356fddcb55d0963a7abd205bc44d752f4f)			

#22 - 2023-12-28 15:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340723	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev_mce	wangxl0510@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptables sepolicy.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: Ia0bc6de5d257964cfe634b27c9815d7d63ec08a9(cherry picked from commit bbfb24356fddcb55d0963a7abd205bc44d752f4f)			

#23 - 2023-12-28 15:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340724	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp_mce	wangxl0510@thundersoft.com

LC:Network: Limit use 2020 port in QSSIAdd iptables sepolicy.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: Ia0bc6de5d257964cfe634b27c9815d7d63ec08a9(cherry picked from commit bbfb24356fddcb55d0963a7abd205bc44d752f4f)(cherry picked from commit 2c9081cd2fca46dc23de89aaab44347ae1701e57)

#24 - 2023-12-28 15:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340725	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev_vx1	wangxl0510@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptable rules.Only 192.168.4.16 can use 2020 port.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I90fe3bccd62b4da14b3e8f5e5f10c0ee7cc0f14b(cherry picked from commit 35ab9e507adf9b58ecd85cdc13915cc83fe7a158)			

#25 - 2023-12-28 15:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340726	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp_vx1	wangxl0510@thundersoft.com
LC:Network: Limit use 2020 port in QSSIAdd iptable rules.Only 192.168.4.16 can use 2020 port.TC-RID: 1201-0400701IssueID: TS-R-DF-119113Change-Id: I90fe3bccd62b4da14b3e8f5e5f10c0ee7cc0f14b(cherry picked from commit 35ab9e507adf9b58ecd85cdc13915cc83fe7a158)(cherry picked from commit 436d3f6ca16718195c739e2297c03308b3a4deb0)			