

Figure - 开发 Dev #119145

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110126 (New): 【MK】【AF】管理总票

开发 Dev # 119107 (New): 【MK】【AF】【HiCar】【TC-RID: 1201-0208001】集成华为HiCar功能

【MK】【MM】【HiCar】【TC-RID: 1201-0208001】音频适配

2023-08-04 17:38 - CD TPM-王祥林

Status:	进行中 In Progress	Start date:	2023-08-30
Priority:	Normal	Due date:	
Assignee:	Multimedia组-RD3_TSCD 梁卿山	% Done:	0%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			
Description			
参考PRD , UX , UI和华为官方文档			
https://thundersoft.feishu.cn/drive/folder/CgrEf2z7LIUeV3dTU1kcHTWannh			
https://developer.huawei.com/consumer/cn/doc/development/HiCar-Guides/audio-management-000000000030782			
Subtasks:			
开发 Dev # 119334: 【MK】【MM】【HiCar】【TC-RID: 1201-0208001】音量适配			New

History

#1 - 2023-08-25 16:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304859	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM:HiCar: Add audio-tts-playbackAdd audio-tts-playbackTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ieb63d994a995771e974f51dea9155aeaab7a2a93			

#2 - 2023-08-25 16:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
306401	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: ADD STREAM_TTS MAPADD STREAM_TTS MAPEnable Audio SplitTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ie3b644605cf48cfe7129a85710c419cfc0d36f9f			

#3 - 2023-08-25 16:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
306414	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	tangyj0127@thundersoft.com

		-dev	
MM:HiCar: HiCar playback without limitationsHiCar playback without limitationsTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I0da92b745122a9433e530e5beb641dbb838f071a			

#4 - 2023-08-25 16:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305055	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
BSP:HiCar: pri_rx_2 dtsi changeTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I28e85c9e158f5900b38c070d62b660fa79480cb5			

#5 - 2023-08-25 16:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305054	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
BSP:HiCar:kona driver add pri_rx_2 portTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I7b1c8a66e233dca3455c77a4e6ac97f403b12c29			

#6 - 2023-08-28 14:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
306972	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM:HiCar: Add tts_playback routesAdd tts_playback routesTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ic308e23478c859baa8837937d68edd1a59dfd7b6			

#7 - 2023-08-29 15:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
307333	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM:HiCar: Fix HiCar Call and Music FocusFix HiCar Call and Music FocusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I2be7d2be309ea7a3e538ef64d6c7d22e03d83783

#8 - 2023-09-01 13:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308967	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: GetPackageName from pidGetPackageName from pidTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: lee82ab143014615755449df180ecba5651cf08bf			

#9 - 2023-09-14 15:00 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from New to 进行中 In Progress

当前要求：

- 1.HiCar的导航音，通知音，铃声，闹钟，系统音，拨号音，回铃音，使用TTS流输出；
- 2.TTS流输出不申请焦点，直接播放；

#10 - 2023-09-14 15:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312769	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:HiCar output strategy changeHiCar output strategy changeTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I5c5ca523a4f075b505f0cd6693ef8bb46f42d02a			

#11 - 2023-09-14 15:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312743	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: TTS Stream not request audiofocusTTS Stream not request audiofocusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ia76bb7ea7acdaae854fe031c657db4d67476e432			

#12 - 2023-09-20 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314421	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: Priority Mute MediaPriority Mute MediaTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I2d82bfeff52273c04da015e69f398194c4e2b0d5			

#13 - 2023-09-21 10:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314722	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: HiCar properties configureBitrate Configuration ChangesTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Iaf9e5ed1efe66761a7a771a57d2be260d12fcd7			

#14 - 2023-09-21 18:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314991	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: Internal Focus do not updatedInternal Focus do not updatedTC-RID: 1201-0208001IssueID: TS-R-DF-119145,VCH-176Change-Id: If363f8b11e4684b1414a6555e550f25805355a95			

#15 - 2023-09-22 14:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314780	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: Modify the way HiCar request focusModify the way HiCar request focusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I88490f081b15aa1e555a6ef619df6b6d64d2034c			

#16 - 2023-10-07 11:32 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
317246	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix volume sync during callsFix volume sync during callsTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I4935039a92a3d52f1be8b077ce67f75a79ad6e62			

#17 - 2023-10-08 11:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317440	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix focus issue during callFix focus issue during callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I4896c473da3d6a5b23a67c2c592bf141fe53e2c6			

#18 - 2023-10-12 17:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318954	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix HiCar WeChat VOIP audiofocus issueFix HiCar WeChat VOIP audiofocus issueTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I1815cc0b82690ea67c23334bfcce79df45ef3f43			

#19 - 2023-10-16 19:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319328	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix mute error when requesting call focus failsFix mute error when requesting call focus failsTC-RID: 1201-0208001IssueID: TS-R-DF-119145,VCH-453,VCH-456,VCH-457Change-Id: Id7061fba8497bcafb4c0d433c5d1089322c384b8			

#20 - 2023-10-16 19:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

319823	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix the incoming voice prompt is silentFix the incoming voice prompt is silentTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I32c631d45401dc725e62d98c49a9d0908cdab7d4			

#21 - 2023-10-17 16:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320044	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix HiCar call focus issueFix HiCar call focus issueTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I7c27283bd46cc28183479dcfcd12fc30b9ee47a5			

#22 - 2023-10-20 20:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321062	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:Fix HiCar Audio StutteringFix HiCar Audio StutteringTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I42b7eeea3b625bc414f2bab0afc17ba9964767e3			

#23 - 2023-10-20 22:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321359	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
Audio:HiCar: enable echo-reference PRI_TX_1 pathTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I279977a0887a4e2a8a8511857f5c6b0f410bdbe5			

#24 - 2023-10-23 20:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321974	general/platform/frameworks/av	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM:HiCar:Use speaker when voice callUse speaker when voice callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I1747d62d156fcceeb62dab18caaed5a33e4d2f25

#25 - 2023-10-23 20:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321953	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
MM:HiCar:enable 4mic fluence pro algorithmenable 4mic fluence pro algorithmTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I665303edb2eafecff58bb0ff20b286979ebefe85			

#26 - 2023-10-24 19:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322348	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM:HiCar:echo-reference enable when HiCar voice callecho-reference enable when HiCar voice callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I844edf5ec363a041baea532e9d17c7f6e72409ac			

#27 - 2023-10-24 19:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322369	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:HiCar usage 3 change to tts-playbackHiCar usage 3 change to tts-playbackTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I8f3a566aa910057da20ff49856faf48f86735c80			

#28 - 2023-10-25 19:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322632	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

MM:HiCar: HiCar playback without limitationsHiCar playback without limitationsTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I0da92b745122a9433e530e5beb641dbb838f071a(cherry picked from commit f3c2fc20a5ae57af89a10a52ea175785e6fad715)

#29 - 2023-10-25 19:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322633	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: Fix HiCar Call and Music FocusFix HiCar Call and Music FocusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I2be7d2be309ea7a3e538ef64d6c7d22e03d83783(cherry picked from commit f6ea0fd7dca0f698a391cde8afbb9833b3066d01)			

#30 - 2023-10-25 19:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322780	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: GetPackageName from pidGetPackageName from pidTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Iee82ab143014615755449df180ecba5651cf08bf(cherry picked from commit f087a90364bcc304d30c51e37b7f64e8c58a4628)			

#31 - 2023-10-26 22:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323032	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: TTS Stream not request audiofocusTTS Stream not request audiofocusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ia76bb7ea7acdaae854fe031c657db4d67476e432(cherry picked from commit 84b513ea41d9bce7285f51933d4fc05767c58be0)			

#32 - 2023-10-27 00:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323222	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

MM:HiCar: Priority Mute MediaPriority Mute MediaTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I2d82bfeff52273c04da015e69f398194c4e2b0d5(cherry picked from commit 977b765deb3ee96f8b746b8c372ae83a8977be42)

#33 - 2023-10-27 00:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323223	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: Internal Focus do not updatedInternal Focus do not updatedTC-RID: 1201-0208001IssueID: TS-R-DF-119145,VCH-176Change-Id: If363f8b11e4684b1414a6555e550f25805355a95(cherry picked from commit 02f0bb5097721815e14dcef8f35c1de30820b850)			

#34 - 2023-10-27 00:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323225	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: Modify the way HiCar request focusModify the way HiCar request focusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I88490f081b15aa1e555a6ef619df6b6d64d2034c(cherry picked from commit 6b1ac91929e32cc12a29d428dd3b68f8a190ef2e)			

#35 - 2023-10-27 00:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323255	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:Fix volume sync during callsFix volume sync during callsTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I4935039a92a3d52f1be8b077ce67f75a79ad6e62(cherry picked from commit 5ddb1c7d042e27be85911173be364c31eaf71b9c)			

#36 - 2023-10-27 01:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323257	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	wangxl0510@thundersoft.com

		-release_sorp	
MM:HiCar:Fix focus issue during callFix focus issue during callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I4896c473da3d6a5b23a67c2c592bf141fe53e2c6(cherry picked from commit bb090a2051b4529b007d82899c69ebabda9ce5e3)			

#37 - 2023-10-27 01:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323266	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM:HiCar:Fix HiCar WeChat VOIP audiofocus issueFix HiCar WeChat VOIP audiofocus issueTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I1815cc0b82690ea67c23334bfcce79df45ef3f43(cherry picked from commit 1f13922cf99502d7a3d0bbca6b8546389a547991)			

#38 - 2023-10-27 01:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323278	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM:HiCar:Fix mute error when requesting call focus failsFix mute error when requesting call focus failsTC-RID: 1201-0208001IssueID: TS-R-DF-119145,VCH-453,VCH-456,VCH-457Change-Id: Id7061fba8497bcafb4c0d433c5d1089322c384b8(cherry picked from commit 3dc8b560f302b30e837b51f8b67a1a7a778be45f)			

#39 - 2023-10-27 01:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323298	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM:HiCar:Fix HiCar call focus issueFix HiCar call focus issueTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I7c27283bd46cc28183479dcfcd12fc30b9ee47a5(cherry picked from commit 1bfaa716561f93a639010ee1d3e7706d88dee640)			

#40 - 2023-10-27 02:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323329	general/platform/frameworks/av	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:Use speaker when voice callUse speaker when voice callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I1747d62d156fccceb62dab18caaed5a33e4d2f25(cherry picked from commit 68be0df76efeb4f23f9304781931473c90334e8e)			

#41 - 2023-10-27 02:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323342	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: Add audio-tts-playbackAdd audio-tts-playbackTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ieb63d994a995771e974f51dea9155aeab7a2a93(cherry picked from commit 511ae0c929667bf0de3d1be15c721b5a879c55c6)			

#42 - 2023-10-27 02:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323343	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:HiCar: pri_rx_2 dtsi changeTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I28e85c9e158f5900b38c070d62b660fa79480cb5(cherry picked from commit 45d2e6b4312ee7169ddb692d29b996906fc1e545)			

#43 - 2023-10-27 02:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323344	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:HiCar:kona driver add pri_rx_2 portTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I7b1c8a66e233dca3455c77a4e6ac97f403b12c29(cherry picked from commit 9b3ffad35e97ad126c3980fde13dcec4c88ac937)			

#44 - 2023-10-27 02:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323345	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: Add tts_playback routesAdd tts_playback routesTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ic308e23478c859baa8837937d68edd1a59dfd7b6(cherry picked from commit aeecccf6a2c447f83a9fbe644d40ab390c4e3544)			

#45 - 2023-10-27 02:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323347	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
Audio:HiCar: enable echo-reference PRI_TX_1 pathTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I279977a0887a4e2a8a8511857f5c6b0f410bdb5(cherry picked from commit 2c7e45b719fec29ea8d068d680ed427c2ca6d13f)			

#46 - 2023-10-27 02:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323348	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:enable 4mic fluence pro algorithmenable 4mic fluence pro algorithmTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I665303edb2eafecff58bb0ff20b286979ebef85(cherry picked from commit 77611b253e144dbf7f05b43db1493c5f3f0c55b2)			

#47 - 2023-10-27 02:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323349	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:echo-reference enable when HiCar voice callecho-reference enable when HiCar voice callTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I844edf5ec363a041baea532e9d17c7f6e72409ac(cherry picked from commit 93ceb2f1b86e5d852bee017d2ead0fcaca6a10f1)			

#48 - 2023-10-31 17:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324399	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:enable MultiAudioBus Policyenable MultiAudioBus PolicyTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I261c075140b0635f3a8c36b30a2c8ad4619f4545			

#49 - 2023-10-31 19:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324489	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:enable MultiAudioBus Policyenable MultiAudioBus PolicyTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I261c075140b0635f3a8c36b30a2c8ad4619f4545(cherry picked from commit 1c7849b8f4da83602b5931c7f9d90e4c739311b8)			

#50 - 2023-11-01 20:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322563	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:HiCar TTS Request FocusHiCar TTS Request FocusTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I00d026ecd0ab1b87e21fa5639d2250d979caa430			

#51 - 2023-11-07 17:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325796	general/platform/frameworks/av	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM:HiCar: STREAM_TTS Volume Policy ChangeSTREAM_TTS Volume Policy ChangeTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I3af69eee2688a5c607d14681b089a6bebdeda76b			

#52 - 2023-11-07 17:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325463	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM:HiCar: audio-tts-playback add bt-a2dpaudio-tts-playback add bt-a2dpTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I73bb7c301f47cd4ae6595a21b5886bb1f8336183			

#53 - 2023-11-07 17:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325461	general/platform/frameworks/av	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: STREAM_TTS output policy changeSTREAM_TTS output policy changeTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I82273f437242d76419b7d529117c945d48ada589			

#54 - 2023-11-07 17:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326089	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar: STREAM_TTS ummute when request grantedSTREAM_TTS ummute when request grantedTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I4bc177a39bfaa8b90f48f43bef6cb7e350079592			

#55 - 2023-11-20 13:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329434	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar: HiCar HwDMSDPDevice updateHiCar HwDMSDPDevice updateTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I327736b1abd56d728b462e53e8080785f12b3ad3			

#56 - 2023-11-20 14:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
328515	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:HiCar HwDMSDPDevice updateHiCar HwDMSDPDevice updateTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: I327736b1abd56d728b462e53e8080785f12b3ad3			

#57 - 2023-12-04 17:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
333278	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:HiCar:ADD NotificationAndMusicADD NotificationAndMusicTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ie700d6874e2ea66dfce5ec364955d7e6263ecc58			

#58 - 2023-12-11 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
334890	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM:HiCar:ADD NotificationAndMusicADD NotificationAndMusicTC-RID: 1201-0208001IssueID: TS-R-DF-119145Change-Id: Ie700d6874e2ea66dfce5ec364955d7e6263ecc58(cherry picked from commit 4a3408e330097e1bb4876eacadd5d84e50fbc4df)			