

Figure - 开发 Dev #119482

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110654 (进行中 In Progress): 【MK】【005】【LCD】主任务

【MK】【005】【LCD】【TC-RID: 1201-0100501】VC1 FSE屏幕日志上云

2023-10-10 17:38 - CD TPM-王祥林

Status:	New	Start date:	2023-10-07
Priority:	Normal	Due date:	
Assignee:	CD TPM-王祥林	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
1.Touch日志：保存触摸的坐标，以及同时按下的触摸点数到文件中。如果是滑动，则只保留起始和结束点信息。			
2.通过IIC读取屏幕状态信息，并且保存到文件。读取从0x40到0x4E所有的信息，具体参考下面的表格。			
https://thundersoft.feishu.cn/file/CfCpbcqmxoYGUNxhqhycejhyn1b			
3.屏幕日志文件单独保存，以FSE_开头，和原有日志一起打包，和以前一样统一由中控来获取上传云端。			

History

#1 - 2023-10-20 11:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320912	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Tlog:Add Selinux permissions to the iic_diagnostics node.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I18eb33e597e33a79c1e690d00dcd25b8ea0afa0f			

#2 - 2023-10-20 11:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320908	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Tlog:add iic log collect functionFirst editionTC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I2bda6dec2448d70878c6d82793d5f2ed8b759e90			

#3 - 2023-10-23 15:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321803	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com

AF:Tlog:Add parsing rules for LCMFaultRecord and FSEFaultRecord.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I33d835fe6aac7682941d8ef04b2cb0b51d2e8133

#4 - 2023-10-25 13:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322258	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Tlog:Add Selinux permissions to the iiclog.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I1d4c4aa538ddb940d969460b30b60713510fd254			

#5 - 2023-10-25 13:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322261	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Tlog:Change the directory for iic log storage.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I04dbfdd51f298caa2e029e222d52f970881279a4			

#6 - 2023-10-25 13:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
322264	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Tlog:add iic point log collect functionTC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I498e4391d1b04d3cda6d2ea5a0480437e52a4112			

#7 - 2023-10-27 01:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323317	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Tlog:Add Selinux permissions to the iic_diagnostics node.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I18eb33e597e33a79c1e690d00dcd25b8ea0afa0f(cherry picked from commit a1b9ddab0828531c0244a2a5014543f1ccdeb871)			

#8 - 2023-10-27 01:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

323318	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog:add iic log collect functionFirst editionTC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I2bda6dec2448d70878c6d82793d5f2ed8b759e90(cherry picked from commit 9b412be9e83e58b4ba2bb0b4a2f0ce531dfdbc22)			

#9 - 2023-10-27 02:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323323	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog:Add parsing rules for LCMFaultRecord and FSEFaultRecord.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I33d835fe6aac7682941d8ef04b2cb0b51d2e8133(cherry picked from commit 16a938b571b85245df5fc3779a85a16d315e2c97)			

#10 - 2023-10-27 02:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323333	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog:Add Selinux permissions to the iiclog.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I1d4c4aa538ddb940d969460b30b60713510fd254(cherry picked from commit 89c89dfce75ad54cbd4ed49284d00dd339f02393)			

#11 - 2023-10-27 02:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323334	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog:Change the directory for iic log storage.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I04dbfdd51f298caa2e029e222d52f970881279a4(cherry picked from commit 44205895473154c7946b4a604bf2f050d5f637c4)			

#12 - 2023-10-27 02:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

323335	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog:add iic point log collect functionTC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I498e4391d1b04d3cda6d2ea5a0480437e52a4112(cherry picked from commit 710049aa055f63da37eb125feb04db190da6a903)			

#13 - 2023-11-09 14:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326935	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Tlog: Capture all exceptions to ensure the proper functioning of IIC logs.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, VCH-518Change-Id: I264b4b24b6ebd96de2cb2113e8e2aeceb521df3d			

#14 - 2023-11-15 16:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
328289	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Tlog: Capture all exceptions to ensure the proper functioning of IIC logs.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, VCH-518Change-Id: I264b4b24b6ebd96de2cb2113e8e2aeceb521df3d(cherry picked from commit d49eb00a44fb32c3f2aa8febd03aba7be9f172bd)			

#15 - 2023-11-20 11:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
328867	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Tlog: Remove count.txt, uefi/*, fota/* after packaged.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, IOVISSUE-17068Change-Id: I8711081355cf77b77dc81e6b21182d91592d537d			

#16 - 2023-11-23 20:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
330682	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:Tlog: Remove count.txt, uefi/*, fota/* after packaged.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, IOVISSUE-17068Change-Id: I8711081355cf77b77dc81e6b21182d91592d537d(cherry picked from commit 743c2030f717244edbfdb0e3ef1da25987e802ff)

#17 - 2023-12-22 14:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318785	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:Display:Add max96755g backlight query node and IIC parameter query nodeModify:1.Add max96755g backlight query node2.:Add max96755g IIC parameter query nodeTest:1.max96755g backlight query node:cd /sys/bus/i2c/devices/0-0040/max96755gcat screen_diagnostics2. max96755g IIC parameter query node:cd /sys/bus/i2c/devices/0-0040/max96755gecho (1 ~ 12) > iic_diagnosticscat iic_diagnostics(1~12) represents query parameters from 0x40 ~ 0x4ETC-RID: 1201-0100501IssueID: TS-R-DF-119482Change-Id: Ie10dfb61728c38dfa210686e8fd51d34ea5bcc93			

#18 - 2023-12-26 09:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
328698	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:Display:Add max96755g backlight query node and IIC parameter query nodeModify:1.Add max96755g backlight query node2.:Add max96755g IIC			

parameter query nodeTest:1.max96755g backlight query node:cd /sys/bus/i2c/devices/0-0040/max96755gcat screen_diagnostics2. max96755g IIC parameter query node:cd /sys/bus/i2c/devices/0-0040/max96755gecho (1 ~ 12) > iic_diagnosticscat iic_diagnostics(1~12) represents query parameters from 0x40 ~ 0x4EChange-Id: Ie10dfb61728c38dfa210686e8fd51d34ea5bcc93TC-RID: 1201-0100501IssueID: TS-R-DF-119482

#19 - 2023-12-27 10:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
338939	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF:Tlog: Do not record IIC point logs during monkey test.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I39800dffde9d0e2fceb3f370f6c1ac4bacf689aa			

#20 - 2023-12-27 23:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340579	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Tlog: Do not record IIC point logs during monkey test.TC-RID: 1200-0800102IssueID: TS-R-DF-119482Change-Id: I39800dffde9d0e2fceb3f370f6c1ac4bacf689aa(cherry picked from commit 5c99031556232b25e2703e0cac38c9216e15bd6d)			

#21 - 2023-12-29 15:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
341152	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:Display:Add max96755g backlight query node and IIC parameter query nodeFix build error.TC-RID: 1201-0100501IssueID: TS-R-DF-119482Change-Id: Ie2fb46ad4ac0aedc8f4ffebf92c02ddeb986fde			

#22 - 2024-02-06 09:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
350350	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Tlog: Capture all throwable exceptions to ensure the proper functioning of IIC logs.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, IOVDEV-52644Change-Id: I5aeae80a866727705e79206846fb96a3d16fa40b			

Gerrit Merge Information :

ID	Project	Branch	Uploader
350348	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Tlog: Capture exception for MotionEvent::getAxisValue.TC-RID: 1200-0800102IssueID: TS-R-DF-119482, IOVDEV-52644Change-Id: Ifbc5f04729ee6a5816f23749f118162b922c4ca0			