

Figure - Bug #119561

【AF】【PVT】【UI】MCE V 150版本中，部分UI与需求不符合

2023-11-01 10:03 - 移动测试一组\_CDTS 刘强

|                                     |                |                   |            |
|-------------------------------------|----------------|-------------------|------------|
| Status:                             | CLOSED         | Start date:       | 2023-11-01 |
| Priority:                           | Normal         | Due date:         |            |
| Assignee:                           | 移动测试一组_CDTS 刘强 | % Done:           | 100%       |
| Category:                           | CD-FW          | Estimated time:   | 0.00 hour  |
| Target version:                     |                |                   |            |
| Need_Info:                          | --             | Found Version:    | MCE 150    |
| Resolution:                         | FIXED          | Degrated:         | No         |
| Severity:                           | Normal         | Verified Version: |            |
| Reproducibility:                    | Every time     | Fixed Version:    | 2023-11-02 |
| Test Type:                          | ST             | Root cause:       | UI 适配问题。   |
| Description                         |                |                   |            |
| 详情参照附件，UI1-UI7 共七项<br>其中以UI命名的图片为需求 |                |                   |            |

History

#1 - 2023-11-01 18:18 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                    | Project                                  | Branch                                    | Uploader                 |
|---------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|-------------------------------------------|--------------------------|
| 324855                                                                                                                                | general/platform/packages/apps/Launcher3 | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | tao.liao@thundersoft.com |
| AF:Launcher: Fix Launcher UI problem.TC-RID: 1201-0205301IssueID: TS-R-BUG-119561Change-Id: I9c779419841b0ae04dc6995cc3c297b23a58b020 |                                          |                                           |                          |

#2 - 2023-11-01 18:18 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                                                                                                    | Project                          | Branch                                    | Uploader                 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------------------------|--------------------------|
| 324853                                                                                                                                                                                                                                | general/platform/frameworks/base | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | tao.liao@thundersoft.com |
| AF:QuickSettings: Fix media control panel problem.1. Fix notification clear button style problem;2. Fix tile edit background problem;TC-RID: 1201-0201903IssueID: TS-R-BUG-119561Change-Id: Ic841b9cc993c53e84d8ed361875cecf779637db3 |                                  |                                           |                          |

#3 - 2023-11-01 18:20 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to 移动测试一组\_CDTS 刘强
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-11-02

- Root cause set to UI 适配问题。

■ Current conclusion

问题 1- 5 已处理，代码已入库。问题 6 是小窗圆角问题，已单独提票，请在对应的票上跟踪，7 是 UI 问题，不处理。

■ Next action

麻烦测试验证。

#4 - 2023-11-02 13:57 - 移动测试一组\_CDTs 刘强

- Status changed from RESOLVED to VERIFIED

问题1-5验证通过，问题保持默认，问题6由119386 跟踪

#5 - 2023-11-02 13:59 - 移动测试一组\_CDTs 刘强

- Status changed from VERIFIED to CLOSED

#6 - 2023-11-03 17:40 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                                                                        | Project                                  | Branch                                             | Uploader                   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|----------------------------------------------------|----------------------------|
| 325514                                                                                                                                                                                                    | general/platform/packages/apps/Launcher3 | Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp | wangxl0510@thundersoft.com |
| AF:Launcher: Fix Launcher UI problem.TC-RID: 1201-0205301IssueID: TS-R-BUG-119561Change-Id: I9c779419841b0ae04dc6995cc3c297b23a58b020(cherry picked from commit 78951d34662c2ce6b87ffd8853a0feeb50ddb7b1) |                                          |                                                    |                            |

#7 - 2023-11-03 17:40 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                                                                                                                                                                        | Project                          | Branch                                             | Uploader                   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|----------------------------------------------------|----------------------------|
| 325516                                                                                                                                                                                                                                                                                                    | general/platform/frameworks/base | Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp | wangxl0510@thundersoft.com |
| AF:QuickSettings: Fix media control panel problem.1. Fix notification clear button style problem;2. Fix tile edit background problem;TC-RID: 1201-0201903IssueID: TS-R-BUG-119561Change-Id: Ic841b9cc993c53e84d8ed361875cecf779637db3(cherry picked from commit 1500a2c79cc444b88ad1a57265e177c960ddca64) |                                  |                                                    |                            |

Files

|        |         |            |                |
|--------|---------|------------|----------------|
| 附件.zip | 3.49 MB | 2023-11-01 | 移动测试一组_CDTs 刘强 |
|--------|---------|------------|----------------|