

Figure - 开发 Dev #119575

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 119585 (New): 【MK】【VX1返装】管理总票

【MK】【006】【Ethernet】【TC-RID: 1201-0400601】865反装项目以太网100M改1000M

2023-11-02 14:18 - CD TPM-王祥林

Status:	New	Start date:	2023-11-02
Priority:	Normal	Due date:	
Assignee:	CD TPM-王祥林	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
按照865反装的要求，以太网需要支持1000M。硬件本身是支持的，软件侧需要在Figure的代码基础上将100M改为1000M。			

History

#1 - 2023-11-06 17:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324933	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[1/6]In force speed mode, modify the network speed from 100M to 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Icccacbe0a7f58c5e6b1147b450d68f247ad812			

#2 - 2023-11-06 17:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324932	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: Network speed 1000M optimization[3/6]Add Gigabit Ethernet network speed optimization.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Ia3db500a51aa51c8129ce10a2c20f44c75077444			

#3 - 2023-11-06 17:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324931	general/platform/system/core	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: Network speed 1000M optimization[4/6]Close selinux and increase permissions in user mode.TC-RID: 1201-0400601IssueID:			

#4 - 2023-11-06 17:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324929	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: Network speed 1000M optimization[6/6]Enable hard interrupt support for large cores.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I7424f31cd8ca2601e9651a1ccb8bdafdc38ccaae			

#5 - 2023-11-06 17:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325202	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[2/6]Add MAC Configuration for 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I2b0f5013ba53b4c1189b71611fdd49cccaf352d7			

#6 - 2023-11-06 17:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
324930	general/platform/vendor/thundercomm/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	kai.zheng@thundersoft.com
BSP:Ethernet: Network speed 1000M optimization [5/6]Enable CPU performance mode.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I09c07d5ac409043a3360ab4165d9c08dffd60ce2			

#7 - 2023-11-09 19:42 - CD TPM-王祥林

- Parent task changed from #110643 to #119585

#8 - 2023-11-14 14:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327632	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com

BSP:Ethernet: Network speed 1000M optimization[3/6]Add Gigabit Ethernet network speed optimization.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Ia3db500a51aa51c8129ce10a2c20f44c75077444(cherry picked from commit c9397eee687756673048742b06e99d2067e90409)

#9 - 2023-11-14 14:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327626	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[1/6]In force speed mode, modify the network speed from 100M to 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: lcecccacbe0a7f58c5e6b1147b450d68f247ad812(cherry picked from commit 7cbbcb69ee6ca80a25c2a13977d6eed771ae0bcf5)			

#10 - 2023-11-14 14:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327762	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[2/6]Add MAC Configuration for 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: l2b0f5013ba53b4c1189b71611fdd49cccf352d7			

#11 - 2023-11-14 17:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327745	general/platform/vendor/thundercomm/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com
Revert BSP:Ethernet: Network speed 1000M optimization [5/6]This reverts commit 1891b367da816bcd29cf2cbc3f74bd30983f765a.Reason for revert: <no need>TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: lc1fb64345b3f80593a158d958d27268b72447709			

#12 - 2023-11-14 17:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327744	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com

Revert BSP:Ethernet: Network speed 1000M optimization[6/6]This reverts commit 5bbc7ffc7edb56c6cbdbd922e90eeeba1d325474.Reason for revert: <no need>TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Iaa5a835385fe014ec2e004fc6a255b160213530

#13 - 2023-11-14 17:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327743	general/platform/system/core	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com
Revert BSP:Ethernet: Network speed 1000M optimization[4/6]This reverts commit 38cdf348b63953ad29853956859331be5b13585f.Reason for revert: <no need>TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I6a397fa4c46697bfa40f12a997176da2d9e48594			

#14 - 2023-11-21 11:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329718	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[2/6]Add MAC Configuration for 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I2b0f5013ba53b4c1189b71611fdd49cccaf352d7(cherry picked from commit acf55d4bbeab82ef7b175173babc1e85a7a4874c)			

#15 - 2023-11-21 11:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329717	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: modify network speed, from 100M to 1000M[1/6]In force speed mode, modify the network speed from 100M to 1000M.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Iceccacbe0a7f58c5e6b1147b450d68f247ad812(cherry picked from commit 7cbbc69ee6ca80a25c2a13977d6eed771ae0bcf5)			

#16 - 2023-11-21 11:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

329536	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: Network speed 1000M optimization[3/6]Add Gigabit Ethernet network speed optimization.TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: Ia3db500a51aa51c8129ce10a2c20f44c75077444(cherry picked from commit c9397eee687756673048742b06e99d2067e90409)			

#17 - 2023-11-21 18:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329435	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com
BSP:Display: MCE PRO will use new hardware and modify EVT1 configurationTC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I95cd99cee9077db88bfecbfcb6d6481c40676c9			

#18 - 2023-11-21 18:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329736	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com
BSP:Display: MCE PRO will use new hardware and modify EVT1 configurationTC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I95cd99cee9077db88bfecbfcb6d6481c40676c9(cherry picked from commit c2e925c561b56bd08b2859680a8a4c786cbf7372)			

#19 - 2023-11-21 18:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329957	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com
BSP:Display: MCE PRO will use new hardware and modify EVT1 configurationTC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I95cd99cee9077db88bfecbfcb6d6481c40676c9(cherry picked from commit c2e925c561b56bd08b2859680a8a4c786cbf7372)(cherry picked from commit ba94a1e17b5fa99bd859fc983c273e91b4bd8654)			

#20 - 2023-12-05 15:12 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
333557	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: Modify 1000M firmware version to 0003.Modify version to 0003TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I984717d37ca9c36ad79bcf4f5f4d9a12be87ed2c			

#21 - 2023-12-05 15:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
333499	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com
BSP:Ethernet: Modify 1000M firmware version to 0003.Modify version to 0003TC-RID: 1201-0400601IssueID: TS-R-DF-119575Change-Id: I984717d37ca9c36ad79bcf4f5f4d9a12be87ed2c(cherry picked from commit 517e2ea65d9fc2f35b70a68eba76fe4ad8b23e26)			