

Figure - 开发 Dev #119576

开发 Dev # 110122 (New): 【MK】 管理总票

开发 Dev # 119585 (New): 【MK】 【VX1返装】 管理总票

【MK】 【011】 【Audio】 【TC-RID: 1201-0101106】 865反装项目Audio时钟和通道数调整

2023-11-02 14:25 - CD TPM-王祥林

Status:	New	Start date:	2023-11-02
Priority:	Normal	Due date:	
Assignee:	CD TPM-王祥林	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
按照865反装项目的要求，A2B的时钟和通道数需要改为8。基于Figure的基础上修改代码。			

History

#1 - 2023-11-09 16:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326983	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-dev_vx1	wangxl0510@thundersoft.com
Audio:BSP: change tdm slot to 8TC-RID: 1201-0101106IssueID: TS-R-DF-119576Change-Id: I06ce0263b682e7f4d8d960fd6254bb150a99673c			

#2 - 2023-11-09 19:42 - CD TPM-王祥林

- Parent task changed from #110647 to #119585

#3 - 2023-11-14 14:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327737	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com
Audio:BSP: change tdm slot to 8TC-RID: 1201-0101106IssueID: TS-R-DF-119576Change-Id: I06ce0263b682e7f4d8d960fd6254bb150a99673c(cherry picked from commit 9a5591db140c0f96abe30922f5077aad39029a51)			

#4 - 2023-11-21 11:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329719	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp_vx1	wangxl0510@thundersoft.com

Audio:BSP: change tdm slot to 8TC-RID: 1201-0101106IssueID: TS-R-DF-119576Change-Id: I06ce0263b682e7f4d8d960fd6254bb150a99673c(cherry picked from commit 9a5591db140c0f96abe30922f5077aad39029a51)

#5 - 2023-11-30 09:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329975	general/platform/vendor/opensource/audio-kernel	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_vx1	wangxl0510@thundersoft.com
Revert Audio:BSP: change tdm slot to 8This reverts commit 8f8ec07c0f2ca15e9bd41f05ff72c787108f808e.Reason for revert: <revert for factory>TC-RID: 1201-0101106IssueID: TS-R-DF-119576Change-Id: I1caa76bcf7d4a9bbd39717ee223e80b90dabc4c8			

#6 - 2023-11-30 09:21 - CD TPM-王祥林

工厂版本先回退。因为没有8550台架，如果用8155调试的话副屏8通道的数据声音会不正常。