

Figure - 开发 Dev #110745

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【APP】【recent】【TC-RID: 1201-0205302】
2022-07-25 20:07 - CD FW-王伟

Status:	进行中 In Progress	Start date:	2022-07-25
Priority:	Normal	Due date:	2022-12-12
Assignee:	CD APP-王宏	% Done:	60%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230		
Description			
■ 需求列表: Recent相关定制 : 后台任务列表 任务选择 任务删除 任务栏Dock栏显示 小窗模式入口 ■ Recent和小窗交互需求更新: 前提条件: 处于Recent界面中 具体要求: 1.点击小窗卡片退出Recent时,需要调用startActivityFromRecents把小窗重新拉起 2.点击其他非卡片时,需要判断小窗Task是否存在,如果存在,调用startActivityFromRecents把小窗重新拉起 3.点击Recent空白区域退出Recent时,需要判断小窗Task是否存在,如果存在,调用startActivityFromRecents把小窗重新拉起 4.点击侧边栏启动其他应用时,不管小窗Task是否存在,都不需要调用startActivityFromRecents把小窗重新拉起 5.在Recent里面,下来通知栏,点击其他应用退出recent时,不管小窗Task是否存在,都不需要调用startActivityFromRecents把小窗重新拉起 ■ 提出URL : 必填 ■ 自测case : 必填 ■ 注意点 : 需要测试注意的前提条件			
Related issues:			
Related to Figure - 需求 Requirement # 111003: 【Locked需求】La...		分析&分解中 In Analysis	2022-08-03 2022-09-30

History
#1 - 2022-08-02 09:30 - CD FW-王伟
- Due date set to 2022-08-10
#2 - 2022-08-02 09:30 - CD FW-王伟
- Assignee set to CD AF-刘浩
#3 - 2022-08-04 19:47 - CD FW-王伟
- Subject changed from 【MK】【053】【recent】【TC-RID: 0301-0205302】 to 【MK】【053】【recent】【TC-RID: 1201-0205302】
#4 - 2022-09-08 08:34 - CD FW-王伟
- Subject changed from 【MK】【053】【recent】【TC-RID: 1201-0205302】 to 【MK】【APP】【recent】【TC-RID: 1201-0205302】
#5 - 2022-09-08 08:38 - CD FW-王伟

- Assignee changed from CD AF- 刘浩 to CD- App- 李朝鹏

#6 - 2022-09-26 19:51 - CD FW-王伟

- Target version set to VX1_MCE_FSE_V3.0_20221030

#7 - 2022-11-22 14:33 - CD APP-王营

- Due date changed from 2022-08-10 to 2022-12-12

- Status changed from New to 进行中 In Progress

- Assignee changed from CD- App- 李朝鹏 to AF组-RD3_CDTs 罗肖

- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V5.0_20221230

- % Done changed from 0 to 60

#8 - 2022-12-05 21:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167158	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiao.luo@thundersoft.com
CommitMessage		FW: Launcher: The small window interacts with four Tasks	

#9 - 2022-12-08 10:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168172	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiao.luo@thundersoft.com
FW: Launcher: The problem with the desktop kill window1.After the problem of the desktop kill window, the empty background cannot be triggered after the process is killed in RecentTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I7eb2413fbe8170005f8999675b06d730fb14f19a			

#10 - 2022-12-08 21:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168594	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiao.luo@thundersoft.com
FW: Launcher: Fix the problem of clicking small windows on the desktop1.Fix the problem of clicking small windows on the desktopTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I199b4f91040644b9d082d46c680a3ac6aa8b2e19			

#11 - 2022-12-08 21:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168737	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiao.luo@thundersoft.com

FW: Launcher: Replace ClearAllImageView background1.Replace ClearAllImageView backgroundTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I026e36f86779055b3191736dff33b543a3c9e2b

#12 - 2022-12-12 09:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169005	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiao.luo@thundersoft.com
FW: Launcher: Modify MoreSmallWindowsContainer and recent1.Modify MoreSmallWindowsContainer background and recent marginTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I8c1106ee83d654aba0aa55ef276b033dd9a862b1			

#13 - 2022-12-12 17:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169559	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lids1211@thundersoft.com
FW:Launcher: Fix Activity leak1. AllAppInfoUtil will hold destroyed activity when activity rebuild.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I655da4a246e8218ef16e7b0008743d70c27d5ce2			

#14 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147938	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-launcher	chaopeng.li@thundersoft.com
FW:Launcher:Recents customization1. Add clear all button to bottom of recents2. Shrink and center the task list3. Add small window listTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I2cb888d09ad933ee9f8db22e153d9b2114c1fdcb			

#15 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148438	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com

FW:Launcher:Recents cumtomization1. Add clear all button to bottom of recents2. Shrink and center the task list3. Add small window listTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I2cb888d09ad933ee9f8db22e153d9b2114c1fdcb

#16 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149770	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	chaopeng.li@thundersoft.com

FW:Launcher:Recents small window and task cumtomization1. Add more small window2. Add click small window icon to open the appTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ib93aeb61aa2a0b2ce568f1a47501765f617d0be3

#17 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149907	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com

FW:Launcher:Fix build error1. revert 922cfb3b3647fc74fef89cdfa1001492a41e2b642. revert df3609e7809dcb8edbc5bdfa5eedd814c5fe5e43. revert 922cfb3b3647fc74fef89cdfa1001492a41e2b64TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ifafcf3cb02249e350dbbcdf15102ac2844f0d1a

#18 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149916	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com

FW:Launcher:Fix build error1. revert 922cfb3b3647fc74fef89cdfa1001492a41e2b642. revert df3609e7809dcb8edbc5bdfa5eedd814c5fe5e43. revert 922cfb3b3647fc74fef89cdfa1001492a41e2b64TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I18ecea3049b92023e248e6fc6e9b1e0eae80a27

#19 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150122	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Recents small window and task customization1. Add more small window2. Add click small window icon to open the appTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ib23074a846beb7d664734e8ff8e5fa7680ef5e50			

#20 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150432	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Recents size adjustment1. Adjust recents according to the latest design drawings2. Modify recents related code according to coding specificationsTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ifdcc9d21a2cebb1e0e6ea4eca5f6d3705d4b4c43			

#21 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153012	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jiao.li_a@thundersoft.com
FW:Launcher: Add free-window-task in the recent task1.Add FreeWindowContainer to display last one free-window task.2.Modify the size of free-window task view.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I386ff126bc3068143c2ca512c38be58f225dcf3c			

#22 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153450	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com

FW:Launcher:Recents task list Customized1. Change the task list to 2 lines2. Change the task list to be accessed from right to left3. Adjust the layout of recents according to the latest ue4. Disable slide down to open task5. Reproduce the task icon6. Add a small window logo to the task and add an open small window event7. Fix the problem that the task list cannot display all tasks after adding the small window areaTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I41fa4a1608f83f6d2ced73cad2525eb8a6b4e19f

#23 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153928	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	jiao.li_a@thundersoft.com
FW:Launcher: Add Remove-Animation for free-window-task1.Add FreeWindowTaskTouchController to handle related operation interception.2.Add animation operations in FreeWindowContainer.java.3.Modify the alignment of the small-window-module in the recent taskbar.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I9705c2486664bbc9f42a0888024c2b7981c48913			

#24 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154558	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	jiao.li_a@thundersoft.com
FW:Launcher: Show hotseat in recent1. Show hotseat in recent.2. Disable some functions of hotseat and folder in recent.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I4b9aa2cba8a6efea71ba2348cda9c8d33ede5ea0			

#25 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154923	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	jiao.li_a@thundersoft.com
FW:Launcher: Modify Enter Taskbar Close Free-Window1. Modify Enter the taskbar to close the small window, exit the taskbar to open the small window.2. Modify the opening mode of the small window to avoid repeated tasks.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I34fa722c332f7ab97b2cf02c570dfcad0059421			

#26 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155087	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jiao.li_a@thundersoft.com
FW:Launcher: Fix free-window-task to remove recurring bugs1. Fix the bug restored by pressing and holding to remove the free window task and returning to the main window.2. Fix the bug in the free window task interface.3.Modify the flag of the free window in the recent taskbar window.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ibc2e6fbacab35d23366ccb76f920c5939b0413			

#27 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155090	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jiao.li_a@thundersoft.com
FW:Launcher: Relayout recent with HOTSEAT_DIR1. Relayout views in recent after changing HOTSEAT_DIR.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I47bf534c13739be36c28c560f935ea9460519392			

#28 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155128	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:Launcher: add launcher force stop packages permission1.add launcher force stop packages permissionTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I85eff4a88863c4f8288e525e3b0dd937437571a9			

#29 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155243	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Block home to recents animation1. Block home to recents animationTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Iea9002ba95bbd29948b3bdb9f9d4af51895a270a			

#30 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155514	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jjiao.li_a@thundersoft.com
FW:Launcher: Fix the bug in the small window of the taskbar1. Modify the top alignment of free window task at 2560 resolution2. When the desktop small window is modified and not closed, it is abnormal to open the small window3. Modify the problem that the space between the task list and the free-window-task in the taskbar is insufficient.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I4b908be6ef2b080fac370298cc21ed38762659eb			

#31 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155951	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Expand the sliding range of task deletion1. Increases the height of the task list2. Modify task list top and bottom row gridTranslationYTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I2bb723a3e0cd4ffdf928890bd2abb9ffd988985d			

#32 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156338	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Recents adapted 25601. Recents layout adapted to 2560 resolution screensTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I05f76acc2ce857c615f12e21c727a960754e55c0			

#33 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159563	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com

FW:Launcher:perfect app to recents animation1. Modify task list gravity left to center2. Perfect the dynamic layout of recentsTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I81a9d259f3b3d2e5e403dfc2b686f0455158b447

#34 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159924	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lids1211@thundersoft.com
FW:Launcher: Adjust animation of remove free window card1. Adjust free window card position and size2. Adjust remove animation3. Encapsulate free window method in FreeWindowHelperTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I574aa57f4a757f5025a490d56f8e901810b373e7			

#35 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160214	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	chaopeng.li@thundersoft.com
FW:Launcher:Rich small window list1. Add vertical bar to small window list title2. Change the background of the small window list3. Adjust the position of the small window list4. Finish More small window buttonTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I544ebd55039c05967c2a5179ede20f633ef72fb8			

#36 - 2023-01-03 16:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173459	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lids1211@thundersoft.com
FW:Launcher: Show dynamic calendar in recent1. Show dynamic calendar in recent.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I0c0bb7e29b8e6dfe13a4d17796f4379002539568			

#37 - 2023-03-14 09:31 - CD APP-王营

- Assignee changed from AF组-RD3_CDTS 罗肖 to CD APP-王宏

#38 - 2023-03-16 19:32 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
187237	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:VC1 Adaptation1.Button of clear all2.small window container3.small window more4.task list card5.left-right modeTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: If6abd485ecf4b2d2ce0af85311534004a344561e			

#39 - 2023-03-17 22:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188173	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:VC1 Adaptation1.workspace2.folder3.add widget4.edit mode5.hotseatTC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I64ba9535a5ee45d4ce3943f79589d1964beb7d5b			

#40 - 2023-05-10 11:40 - CD FW-鲁凯峰

- Description updated

#41 - 2023-05-10 20:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196496	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:adapter small windowTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I43018134bccabfa366d1ddffb780733b43ad8478			

#42 - 2023-06-27 18:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210523	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

AF:Launcher:Fixed small window dismiss when drag recentTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-32947Change-Id: I6115b30bd9f4636dec52708c50e1beae2a424bba

#43 - 2023-06-27 21:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210593	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Fixed small window dismiss when drag recentTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-35991Change-Id: I6115b30bd9f4636dec52708c50e1beae2a424bba(cherry picked from commit 2386a4e1c368c4ac08189d22096c25860aee05d6)			

#44 - 2023-07-05 16:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212387	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:Launcher: Adding enhanced logging to the swipe up gestureTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I6e074b08ce1cff372da96e16bbba1f07b0d1b74a			

#45 - 2023-07-06 19:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212791	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:Launcher: Adding enhanced logging to the swipe up gestureTC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: I6e074b08ce1cff372da96e16bbba1f07b0d1b74a(cherry picked from commit c7f901f082357c3fceb84c4c5c25674d3a588e67)			

#46 - 2023-07-20 16:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216055	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:checkbox error in recentsTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36270Change-Id: Ic26c40b9a44c03ba6ae8a8aeb10300ac6e625a0f			

#47 - 2023-07-27 23:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218254	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher:checkbox error in recentsTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36270Change-Id: Ic26c40b9a44c03ba6ae8a8aeb10300ac6e625a0f(cherry picked from commit 3caba2de7a42857e0f18fb6a4b6b020805e5af67)			

#48 - 2023-08-03 17:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213456	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Add logs and optimize thumbnail generation logicTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36496Change-Id: I7b1d0d44f98eff66e0efe7bfb43d050f30c0bf7b			

#49 - 2023-08-03 17:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213630	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Reduce the frequency of calls to the status of the small windowTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-38825Change-Id: I75acd4f07b10008804b29eb6b38c2862d3854475			

#50 - 2023-08-04 17:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300388	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Solving the issue of recent animation getting stuckTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36522Change-Id: I0b275bed8b33bac39e23508c28d349ce5ec77c76			

#51 - 2023-08-10 20:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
144189	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12	hong.wang_a@thundersoft.com

	her3	-dev	
AF:Launcher:Add logs and optimize thumbnail generation logicTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36496Change-Id: I7b1d0d44f98eff66e0efe7bfb43d050f30c0bf7b			

#52 - 2023-08-10 20:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302377	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Reduce the frequency of calls to the status of the small windowTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-38825Change-Id: I75acd4f07b10008804b29eb6b38c2862d3854475(cherry picked from commit b092b757abeadf2f507febb49c8d76b828f27880)			

#53 - 2023-08-10 20:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302382	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Solving the issue of recent animation getting stuckTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36522Change-Id: I0b275bed8b33bac39e23508c28d349ce5ec77c76(cherry picked from commit 89166a4ff053016c6b53f2634add9e768b07777b)			

#54 - 2023-09-06 17:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
310337	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF:Launcher: fix recent empty uiAdd logic to clear free task.TC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-40559Change-Id: I89f4528a8d919db3e3f9e0f69c06d4a38c21076f			

#55 - 2023-09-08 14:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
311070	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com

AF:Launcher: Manually refresh the recent tasks list.TC-RID: 1201-0205302IssueID: TS-R-DF-110745, IOVDEV-40635Change-Id: I9dccc47d7f081eb4e2cb3b885362092eb2fadace

#56 - 2023-09-19 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313381	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:Launcher: recent ui adaptationAdapte VX 、 VC1.Free list container.2.RecentViews task list.3.Task bg and size.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: Ia0f8f663cd3b777769552851832f669ccb264aa			

#57 - 2023-09-20 20:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314640	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher: recent ui adaptationAdapte VX 、 VC1.Free list container.2.RecentViews task list.3.Task bg and size.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: Ia0f8f663cd3b777769552851832f669ccb264aa(cherry picked from commit dd7de8920666b1075d4817ee99068d0c693c214f)			

#58 - 2023-09-25 00:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315611	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher: ui adaptationFix build error.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I57ea44107227af7d752efe72f4b36f10df307a2c			

#59 - 2023-10-07 11:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

317145	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher: fix recent empty uiAdd logic to clear free task.TC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-40559Change-Id: I89f4528a8d919db3e3f9e0f69c06d4a38c21076f(cherry picked from commit 4f916c8e7f4bd56dbcc59219fa1e4bc76c0cc241)			

#60 - 2023-10-07 11:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317228	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher: Manually refresh the recent tasks list.TC-RID: 1201-0205302IssueID: TS-R-DF-110745, IOVDEV-40635Change-Id: I9dccc47d7f081eb4e2cb3b885362092eb2fadace(cherry picked from commit 22c5236c1814ae26d991815a3acef27b85bc6fe5)			

#61 - 2023-10-10 17:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318184	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:Launcher: fix taskview uiFix issue:1.TaskView white edge problem.2.TaskView focus conner.TC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-44717、 IOVDEV-44723Change-Id: I19dc0523469bb666243f89ed912c741b51393fe7			

#62 - 2023-10-12 17:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318355	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:Launcher: home ui adaptationAdaptation mce.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I7170f4d2034116cff53e389c3a8298fdd9a31ef8			

#63 - 2023-10-12 17:41 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
318392	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF:Adaptivelcon: icon corner adaptation(2)Adaptation mce.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I51e5d6d7e6425536724a96a337b40f04feb7900			

#64 - 2023-10-12 17:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318926	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF:Launcher: recent ui adaptationAdapte mce.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ia2f1c3e8b4146ab14c4fece1c003fc4635f890e6			

#65 - 2023-10-12 22:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319123	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher: fix taskview uiFix issue:1.TaskView white edge problem.2.TaskView focus conner.TC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-44717、 IOVDEV-44723Change-Id: I19dc0523469bb666243f89ed912c741b51393fe7(cherry picked from commit 6ef857e02ae053ff09c5fb0c65d18f83a8cdc4c2)			

#66 - 2023-10-27 01:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323288	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher: home ui adaptationAdaptation mce.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I7170f4d2034116cff53e389c3a8298fdd9a31ef8(cherry picked from commit cff0e1f95172b595ce271936578f4a4ac91f4a9e)			

#67 - 2023-10-27 01:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323289	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:AdaptiveIcon: icon corner adaptation(2)Adaptation mce.TC-RID: 1201-0205301IssueID: TS-R-DF-110745Change-Id: I51e5d6d7e6425536724a96a337b40f04feb7900(cherry picked from commit 66f66194d0c793b83fe8c158ddad06adeb195687)			

#68 - 2023-10-27 01:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323290	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher: recent ui adaptationAdapte mce.TC-RID: 1201-0205302IssueID: TS-R-DF-110745Change-Id: Ia2f1c3e8b4146ab14c4fece1c003fc4635f890e6(cherry picked from commit 6c60298057a90744e6a38caa689d15852d9ac815)			

#69 - 2023-10-27 10:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323424	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Launcher:Add logs and optimize thumbnail generation logicTC-RID: 1201-0205302IssueID: TS-R-DF-110745,IOVDEV-36496Change-Id: I7b1d0d44f98eff66e0efe7bfb43d050f30c0bf7b(cherry picked from commit 1febbf815970c6a7936d4f4eee961107d32c1e5d)			

#70 - 2023-11-28 15:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
331726	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Launcher: Fix recent small window apps list font size problem.TC-RID: 1201-0205302IssueID: TS-R-DF-110745, IOVDEV-49229Change-Id: Ie56e2847a132d53e536b7e98619953163a7e3cd9			

Gerrit Merge Information :

ID	Project	Branch	Uploader
334885	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher: Fix recent small window apps list font size problem.TC-RID: 1201-0205302IssueID: TS-R-DF-110745, IOVDEV-49229Change-Id: Ie56e2847a132d53e536b7e98619953163a7e3cd9(cherry picked from commit 35fc45c9f09e96fa2124a1063728b799f167386b)			