

Figure - 开发 Dev #111223

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 111116 (New): 【MK】【LC】管理总票

【MK】【001】【BT】【TC-RID: 1201-0400119】BT bringup

2022-08-11 20:10 - CD LC-徐玺栋

Status:	New	Start date:	2022-08-11
Priority:	Normal	Due date:	
Assignee:	CD LC-徐玺栋	% Done:	0%
Category:	LC	Estimated time:	0.00 hour
Target version:			

Description

请填写信息：

■需求列表:

<https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc>

■提出URL：必填

■自测case：必填

■注意点：需要测试注意的前提条件

History

#1 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
142228	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xidong.xu@thundersoft.com

Bluetooth: bluetooth bringupIntegrate htbtfw20.tlv and htnv20.binTC-RID: 1201-0400119IssueID: TS-R-DF-111223Change-Id: I8ef42059a0df2da1a6754cda1d9e0d474cf989fc

#2 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
143429	general/btfm_proc_hst	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xidong.xu@thundersoft.com

BSP:LC:Update Bluetooth calibration files[8/17]update htnv20.binTC-RID: 1201-0400119IssueID: TS-R-DF-111223Change-Id: I1b2c1344c0e98892d7e8e5e9a62d82b21f567499