

Figure - 需求 Requirement #111230

需求 Requirement # 110107 (New): 【Locked需求】总票
需求 Requirement # 110997 (分析&分解中 In Analysis): 【Locked需求】Launcher UI需求
【Locked需求】Launcher UI需求-待机屏保功能
2022-08-12 15:31 - 方案组-RD3_CDTs 王浩云

Status:	分析&分解中 In Analysis	Start date:	2022-08-12
Priority:	Normal	Due date:	2022-10-19
Assignee:	CD APP-王营	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Description			
1. 屏保展示方式： - 通过走马灯（即定时轮播）形式的展示所选择的屏保，若所选屏保只有一张图片，则该图片一直展示			
2. 屏保设置： - 设置路径：setting-显示-屏保 - 屏保时机设置：在屏保设置中进行屏保时机的设置，在亮屏待机状态下，无应用打开运行，选择屏保生效的时机：20s，60s（默认项），2min，3min，5min，10min			
3. 屏保选择： - 自带屏保：选择系统提供的图片作为屏保 - 时钟屏保：选择当前的时钟作为屏保 - 活动主题屏保（默认项）：选择云端下发的活动主题素材作为屏保，主题可多选 - 自定义屏保： 1. 选择相册图片 2. 选择自定义上传图片			
4. 本地机制： - 删除机制：对于过期，下架，撤回的活动主题屏保，需要立即进行素材删除并保留首张素材的缩略图，并打上失效的标签，缩略图到期7天后自动删除，用户再次进入提示：***屏保素材已到期删除 - 补进机制：当主题已设置的所有主题活动到期后，屏保素材剩下，默认补进生效素材中的第一个主题活动作为屏保。			
5. 接口联动： - 副屏需要从中控获取活动主题屏保的下载地址 - 副屏需要从中控获取活动主题屏保的生效时间及到期时间，判断屏保是否在有效期内 - 副屏需要从中控获取用户自定义上传的屏保图片地址，并且下载，存放至副屏，用户可以选择 - 下载状态，需要反馈状态至中控，中控返回至云端			
6. 进入屏保得方式： - 满足屏保时机，进入屏保 - 控制中心，电源选项，进入屏保 - 手机app下发指令，进入屏保			
7. 退出屏保方式： - 向上滑动屏幕，解除屏保，上滑作为统一返回手势			
需求PRD链接： https://thundersoft.feishu.cn/docs/doccn80x4252yfuTtqFzwkSqrcf#			
参考4.1.5章节内容			

History

#1 - 2022-08-15 17:09 - 方案组-RD3_CDTs 王浩云
- Assignee changed from FW&MW2组_DLTS 刘显鹤 to CD APP-王营

#2 - 2022-12-05 21:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167442	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	huangpeng1216@thundersoft.com

	m/apps/ScreenSaver	-dev	
CommitMessage	FW:ScreenSaver: Midify screensaver list item space and scrollbar style		

#3 - 2022-12-05 21:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167641	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
CommitMessage	FW:ScreenSaver: Add Custom local picture apply logic		

#4 - 2022-12-08 10:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167696	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Modify toast style and add list fade effect1.Modify toast style and add list fade effectTC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: I2b1a264a5dceb16105e9747f9afe75d9678545ef			

#5 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154184	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver:Add base mvvm code and main page1.Add base mvvm code2.Add main pageTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I4d4faf94edfd31db693d75890e3e133f0b083fa4			

#6 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154879	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add Clock ScreenSaver1.Add Clock ScreenSaver2.Add Kotlin SupportTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ie076803a6bc63847359d3014742e7e0abbb1a9be			

#7 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154920	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add screensaver Clock UI logic1.Add screensaver Clock UI logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I589933979c39caadabfd97398cb09cedc6162da			

#8 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155289	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Remove Androidx databinding1.Remove androidx databinding2.Add libBase AAR3.Add libMvvm AARTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I6aa433dbe72d7165634dce401bd3c941ba8bc331			

#9 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155380	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add Android.pb support system build1.Add Android.pb support system build2.Support kotlin and Androidx build3.Add SettingsLib Supprtc-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I64c6db3936b4d487668c34cf50aeb8587a9d7027			

#10 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155388	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add screensaver clock preview1.Add screensaver clock previewTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id:			

#11 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155933	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
FW: ScreenSaver: Add ScreenSaver to mk file1.Add ScreenSaver to mk file and build in system.Change-Id: If1d19c18db0e33cb19d6c668d3b8c5c52fbc6207TC-RID: 1201-0300602IssueID: TS-R-DF-111230			

#12 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156221	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
APP:ScreenSaver: Add Android bp for ScreenSaver1.Add Android.bpTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I9cf081939d7a87afb8ecc4266cf3958858fbcddc1			

#13 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157526	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Reconstruct screensaver code structure1.Reconstruct screensaver code structure3.Add phototable moduleTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I67c5f0d53f1d9cf0749b799b57d80fbaed088164			

#14 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157804	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com

FW:ScreenSaver: Add ScreenSaver theme api request logic1.Add ScreenSaver theme api request logic3.Add theme api testTC-RID: 1201-0300602IssueID:
TS-R-DF-111230Change-Id: I5f494514da8aae163c006cc58a11418eb56f3f69

#15 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157971	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add ScreenSaver theme api sign logic1.Add ScreenSaver theme api sign logic2.Add Sign API HttpInterceptorTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ic2f12a7d0e1e67df8ad960059e6ad8648467814a			

#16 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157974	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Hide screensaver application icon in launcher1.Hide screensaver application icon in launcherTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ibe5f3fa3293f3586500d1918548087fe08218fa7			

#17 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158024	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add third parties library for system build1.Add Rxjava jar2.Add Retrofit jar3.Add OkHttp jar4.Add Glige Jar5.modify Android.bpTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Iec9ac01eadcc74f89751a6923acbc101a303a761			

#18 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158504	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com

FW:ScreenSaver: Add System ScreenSaver main page logic1.Add System ScreenSaver main page logicTC-RID: 1201-0300602IssueID:
TS-R-DF-111230Change-Id: I1a6ec1f3bed4aeb85bd7cbd3a19814845929cde9

#19 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158669	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add system screenSaver assets and service1.Add system screenSaver assets2.Add system screenSaver DreamService3.Add system screenSaver apply logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I69f8321951a9cad460ce38e141bf233693af3f74			

#20 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158691	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
AF:Screensaver: Replace screensaver entry to custom1.Replace screensaver entry to customTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I6b72b97adeaa4759830afbedbf43f7aa39c2f6a4			

#21 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159007	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Dynamically add screensaver page1.Dynamically add screensaver page2.Configuring System Dependencies3.Add system build signTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I053d65e8e4665a55ea1dcea89ab78af0de14f75f			

#22 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

159084	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add system and clock screensaver apply logic1.Add system and clock screensaver apply logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I80002d9c10607494b0d9a698dc35adf676dc5abd			

#23 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159111	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add screensaver init page1.Display the corresponding page according to the current screensaver type2.Add system screensaver select statusTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I0ebaacbcd24edc3342eb0cb7f6c3a5743e901a			

#24 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159179	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Change default screensaver1.Change default screensaverTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I910b15968ecf3d12e309100e2d3677234c58cdfd			

#25 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159267	general/platform/vendor/thundercom m/overlay	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Change default screensaver in overlay1.Change default screensaver in overlayTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I6759ec84a36a924f77875753e026ed338a8817b5			

#26 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
159423	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add system and clock screensaver preview logic1.Add system screensaver preview logic2.Add clock screensaver preview logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I23bc7d1c533df60578efd66bb9a98881c2a7ee7e			

#27 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159672	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add system and clock screensaver apply status1.Add system and clock screensaver apply status2.Adjust kotlin versionTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: If6eb642004430d5091bb69c5ab4ea29937653ec7			

#28 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159682	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add system and clock screensaver applied icon1.Add system and clock screensaver applied iconTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I7837c60234a2965ff1d298da3b7154fc935d9c7b			

#29 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159825	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add immersive status bar and navigation bar1. Add immersive status bar and navigation barTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Id2c3591a36ae556c5b1fde5a9e20db2f4e498db6			

#30 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159861	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Unified screensaver resources1. Unified screensaver resourcesTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: ldbfcc6251f4a9f5af26b429cb3f1934cac087464			

#31 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159951	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add theme screensaver base page1. Add theme screensaver base pageTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: l2a4d5368ae8695885a60002d699dc6c6bff6e7ff			

#32 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160302	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add theme screensaver page logic1. Add theme screensaver page default theme logic2. Aad theme screensaver page default theme detail page logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: l30bda2495c3debfa3fd8c2e0274dcc9b71158601			

#33 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160361	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Modify radiobutton style1. Modify radiobutton styleTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: l18c7f4225a56d244d87d27f11ec7cdd82a0affc9			

#34 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160588	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add theme screensaver data logic and apply1. Add theme screensaver base data logic2. Add theme screensaver apply logic3. Add theme screensaver subscribed view4. Add current applied theme titleTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: If963b50fcee40e1d36d6850b26577d3a9890efc3			

#35 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160739	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add theme subscribe logic1. Add theme subscribe logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I36ddbacc1ac3022c383cf65f7e5830a027fd5055			

#36 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160774	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add theme detail select and unselect logic1. Add theme detail select and unselect logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I9ce0a941c6ec72f8fcd35e8dfa0c55dfec0ba58			

#37 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160995	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com

FW:ScreenSaver: Add theme theme preview page1. Add theme theme preview page2. Add fragment navigation logic3. Remove DetailActivity4. Add theme preview logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ic54b7e56d6545590f0c6426e829c572c791ea11b

#38 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161207	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Reconstruct screensaver preview logic1. Reconstruct screensaver theme preview logic2. Reconstruct screensaver system preview logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I803326ac5e4bbea038793b714f7fdd065175439e			

#39 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161384	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add page back press logic1. Add page back press logicTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I5b4fad8056ec9f49534d1fe8c643a8de92d5ceb8			

#40 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161566	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add simulated preview clock page1. Add simulated preview clock page2. Fix first in screensaver crash bugTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I65a708dd0a45a38b73ab35b7ff05f80c2d83f954			

#41 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162222	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com

FW:ScreenSaver: Adjust screensaver theme style1. Adjust screensaver theme styleTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I1cfd6233bdf2687ad1e4824f7dea91134708f9ac

#42 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162223	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Modify gitignore file and commit templete1. Modify gitignore file and commit templeteTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I9a8329a0d9e7ceefb4a5c3ec92fe48319b7abce1			

#43 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162227	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add page jump anim1. Add page jump animTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Iaa57a09fbb66046325ee486926023531cd0db14c			

#44 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162230	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Add custom screensaver basic page1. Add custom screensaver basic page2. Add custom screensaver basic serviceTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I010070606571b5a07d90a8b563fba643f9b60244			

#45 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162234	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	huangpeng1216@thundersoft.com

FW:ScreenSaver: Add custom screensaver other picture logic1. Add custom screensaver other picture logic2. Add custom screensaver other picture
previewTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I1d44446474e75e5a531c836f5f100b8aaab7ba8e

#46 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
164556	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:ScreenSaver: Optimize all click events of screensaver1. Optimize all click events of screensaverTC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: Ia0db539de407a58c82a7258459e851ce9cdb7f43			

#47 - 2022-12-22 20:55 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
165164	general/platform/vendor/thundercom/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
FW: ScreenSaver: Change keystore1. Change a new keystore for screensaver.TC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: I45611d330dc020ef4ef29545ed9912c35e116061			

#48 - 2023-03-09 20:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186346	general/platform/vendor/thundercom/overlay	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
AF: ScreenSaver: Modify default screensaver1.Change default screensaver to system screensaver.TC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: Iea6e4a30d24237dc35f4c807beae83481bad7f18			

#49 - 2023-06-20 15:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208507	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com

Revert AF: ScreenSaver: Disable statusBar touch in DreamActivityThis reverts commit 49fbf61588332b8ff86b2ecaa007530a0e1cf43a.Reason for revert: Customer want to remove this featureTC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: Ic439303e0f1fa4e95abc563f661e8d9bf0d34e1f

#50 - 2023-06-20 15:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208543	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
AF: ScreenSaver : Close screen after dream started 5 seconds1.Single touch can exit screensaver.2.Close screen after dream started 5 seconds later.TC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: If8fa550556af84af38c33f0ea148b310f96bb9fd			

#51 - 2023-06-25 21:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209662	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert AF: ScreenSaver: Disable statusBar touch in DreamActivityThis reverts commit 49fbf61588332b8ff86b2ecaa007530a0e1cf43a.Reason for revert: Customer want to remove this featureTC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: Ic439303e0f1fa4e95abc563f661e8d9bf0d34e1f(cherry picked from commit eed92f0ac270140961abe896beaa80428d730715)			

#52 - 2023-06-26 11:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209695	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF: ScreenSaver : Close screen after dream started 5 seconds1.Single touch can exit screensaver.2.Close screen after dream started 5 seconds later.TC-RID: 1201-0300601IssueID: TS-R-DF-111230Change-Id: If8fa550556af84af38c33f0ea148b310f96bb9fd(cherry picked from commit 2b03a8a697eeeb94ccd4c3c3e72117cf362434b9)			

#53 - 2023-07-12 14:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

214174	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hong.wang_a@thundersoft.com
AF:ScreenSaver:modify default pic when pic load errorTC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-37702Change-Id: I6a769239f54c772170b10630132f3e4a923cadb8			

#54 - 2023-07-13 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214745	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:modify default pic when pic load errorTC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-37702Change-Id: I6a769239f54c772170b10630132f3e4a923cadb8(cherry picked from commit d7ae954a65e658cc4dc595f8dcdd3c295999f6ff)			

#55 - 2023-08-11 13:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302533	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:ScreenSaver:Fix the issue of screen flickering when the screensaver automatically turns off.TC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-39493Change-Id: I8584bdc536090e3e221fc34e2edf0777b809b8f			

#56 - 2023-08-14 18:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303208	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:Fix the issue of screen flickering when the screensaver automatically turns off.TC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-39493Change-Id: I8584bdc536090e3e221fc34e2edf0777b809b8f(cherry picked from commit 66516bc39c8a1ac628b0ba5778fe466eec53a0d5)			

#57 - 2023-09-11 22:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
311569	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com

AF:ScreenSaver:Add an option switch for automatically turning off the screen in screensaver mode.TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ib5176d52a1c971693c08eda3ee60dcbe45ff325

#58 - 2023-09-11 22:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
311571	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:ScreenSaver:Add an option switch for automatically turning off the screen in screensaver mode.TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I463f220c9a88e6ff0ffb9cb80754be718b6ed794			

#59 - 2023-09-22 11:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314523	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:ScreenSaver:VC1 UI V1.2TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I80fa6866f8c701cd88b7e0e691e453cc74c1692b			

#60 - 2023-09-24 12:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315504	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:VC1 UI V1.2TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I80fa6866f8c701cd88b7e0e691e453cc74c1692b(cherry picked from commit 23b348d5555fe1da51ead4efea0af533b43831dd)			

#61 - 2023-10-07 11:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317229	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:Add an option switch for automatically turning off the screen in screensaver mode.TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: Ib5176d52a1c971693c08eda3ee60dcbe45ff325(cherry picked from commit 66424644d140dfd39e509a47c25694206c948c31)			

#62 - 2023-10-07 11:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317230	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:Add an option switch for automatically turning off the screen in screensaver mode.TC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I463f220c9a88e6ff0ffb9cb80754be718b6ed794(cherry picked from commit 064d2d43a9f137fa720be879ab639aee71b0a20)			

#63 - 2023-10-12 15:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318534	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:ScreenSaver:fix redundant round lineTC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-44746Change-Id: I5f00fa0df580b1b95b4ac62d53578477b7057969			

#64 - 2023-10-24 09:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321317	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:ScreenSaver:MCE UI 2.11.MCE ui 2.12.change sw683dp to sw720dpTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I33176a2d645daa0ecc0488f31c3f76701ddddc32			

#65 - 2023-10-27 01:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323285	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:fix redundant round lineTC-RID: 1201-0300602IssueID: TS-R-DF-111230,IOVDEV-44746Change-Id: I5f00fa0df580b1b95b4ac62d53578477b7057969(cherry picked from commit 57f603230c30e7e538c845a78a0f9fce9cb52097)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
323330	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:MCE UI 2.11.MCE ui 2.12.change sw683dp to sw720dpTC-RID: 1201-0300602IssueID: TS-R-DF-111230Change-Id: I33176a2d645daa0ecc0488f31c3f76701dddc32(cherry picked from commit cd467686064d91a44c6927b4b62c7a6bf16d51bf)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
324066	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:ScreenSaver:fix redundant round lineextend the vc1 commit to mceTC-RID: 1201-0300602IssueID: TS-R-DF-111230 IOVDEV-44746Change-Id: I2f6e5d86367eae397a0b321e2d0733a86c3d9ae6			

Gerrit Merge Information :

ID	Project	Branch	Uploader
324488	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:fix redundant round lineextend the vc1 commit to mceTC-RID: 1201-0300602IssueID: TS-R-DF-111230 IOVDEV-44746Change-Id: I2f6e5d86367eae397a0b321e2d0733a86c3d9ae6(cherry picked from commit 2145d491cecb4f800c29c88f1ffcd7d3094779f)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
327711	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:ScreenSaver: Modify text of no more data.TC-RID: 1201-0300602IssueID: TS-R-DF-111230, QMV-761Change-Id: I709b8ae8aa9779454e4a4aed5b6a40619b23e7e7			

#70 - 2023-11-15 19:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
328509	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:ScreenSaver:fix redundant round lineTC-RID: 1201-0300602IssueID: TS-R-DF-111230 IOVDEV-44746Change-Id: I9005a3cd996c841dc584ef49cc6b1e88f517101b			

#71 - 2023-11-17 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329041	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:fix redundant round lineTC-RID: 1201-0300602IssueID: TS-R-DF-111230 IOVDEV-44746Change-Id: I9005a3cd996c841dc584ef49cc6b1e88f517101b(cherry picked from commit daf3e8540b049ee45a2f8b4e71b8eda3e0a3fe90)			

#72 - 2023-11-20 13:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329422	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver: Modify text of no more data.TC-RID: 1201-0300602IssueID: TS-R-DF-111230, QMV-761Change-Id: I709b8ae8aa9779454e4a4aed5b6a40619b23e7e7(cherry picked from commit 375cdf42358c47eec0f3890b8b53b05701a6c552)			