

Figure - Bug #111680
OTA升级失败

2022-09-02 13:18 - IOT-SP-RD 宋洋洋

Status:	CLOSED	Start date:	2022-09-02
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930	Found Version:	服务器版本没有OTA包，本地版本验证
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Bring Up Test		
Description			
服务器上没有生成OTA包，本地编译版升级，升级后，重启设备会进入9008			

History

#1 - 2022-09-14 11:34 - CD TPM-申艳艳

- Category set to BSP

#2 - 2022-09-27 11:04 - CD BSP-杜磊

- Status changed from New to RESOLVED

- Assignee set to CD BSP-杜磊

#3 - 2022-09-27 11:05 - CD BSP-杜磊

- Assignee changed from CD BSP-杜磊 to CDTS_TEST 王成

请最新版本验证一下次问题是否已经解决。没有问题则关闭

#4 - 2022-10-09 17:56 - CD BSP-杜磊

- Target version set to VX1_MCE_FSE_V2.0_20220930

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

#5 - 2022-10-09 17:59 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

#6 - 2022-10-09 18:00 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

OTA功能已正常

#7 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
146461	general/vendor/thundercomm/produc	Pre_figure_turbox-c2130c-la1.I-I-vendo	yepeng0322@thundersoft.com

	ts/figure	r-dev	
BSP:OTA: Modify BoardConfig.mk for update BP partitions.Modify BoardConfig.mk for update BP partitions.IssueID: TC-R-DF-111680TC-RID: 1201-0100805Change-Id: I9fd5f3a378776e19229d3af20bb0147f45137d86			

#8 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
146547	general/turbox/tools/build_script/platform	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:OTA: Modify build_hlos.sh to generate FOTA package and merged target package.Modify build_hlos.sh to generate FOTA package and merged target package.IssueID: TS-R-DF-111680TC-RID: 1201-0100805Change-Id: I86b5d78591b3fbe394761a62f9046d296472703c			

#9 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153484	general/turbox/tools/build_script/platform	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:OTA: Modify scripts for build the three bp-images.Modify scripts for build the three bp-images.IssueID: TS-R-DF-111680TC-RID: 1201-0100805Change-Id: Ic3004ed5074c95dc4a2b6c5fe8a34cb953d20661			