

Status:	CLOSED	Start date:	2022-09-05
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925	Found Version:	2022.08.25版本
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Occasionally	Root cause:	
Test Type:	Release Test		
Description			
DC12V/14V上电，VX1显示屏概率性有时不亮需要重启才会量			

History

#1 - 2022-09-14 11:20 - CD TPM-申艳艳
- Category set to BSP
- Assignee changed from 软件二组_SD3 朱彦斌 to CD BSP-余霄

Hi 余霄，
帮忙确认一下问题状态，如果没有问题走关闭流程，谢谢

#2 - 2022-09-15 18:41 - CDTS-TEST 周婷
- Target version set to VX1_MCE_FSE_V1.0_update_20220925

#3 - 2022-09-15 18:59 - CD BSP-余霄
- Assignee changed from CD BSP-余霄 to CDTS_TEST 王成

EVT2已改版，供电由SOC来提供。
EVT1使用GPIO拉高

#4 - 2022-09-20 15:05 - CDTS_TEST 王成
- Assignee changed from CDTS_TEST 王成 to CD SYSTEM-赵正军

#5 - 2022-09-21 11:04 - CD TPM-申艳艳
- Category changed from BSP to SYSTEM

#6 - 2022-09-21 11:12 - CD SYSTEM-赵正军
- Category deleted (SYSTEM)
- Assignee changed from CD SYSTEM-赵正军 to CDTS_TEST 王成

问题owner指派错误，还请确认

#7 - 2022-09-21 11:24 - CD TPM-申艳艳

- Category set to BSP

- Assignee changed from CDTS_TEST 王成 to CD BSP-余霄

#8 - 2022-09-21 11:59 - CD BSP-余霄

- Status changed from New to RESOLVED

- Assignee changed from CD BSP-余霄 to SZTS_TEST 邹涛

请帮忙确认验证结果，相关Code已入库

<https://dev.thundercomm.com/gerrit/c/general/kernel/msm-4.19/+146503>

<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+146502>

#9 - 2022-09-23 15:56 - CDTS_TEST 刘勇

测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220923.alpha_0017

测试机器：VX1-GPIO修改

测试次数：120次

测试步骤：

DC12V/14V上电，查看VX1显示屏常亮

实际结果：DC12V上电，VX1不会出现黑屏或不亮

#10 - 2022-09-24 19:30 - SZTS_TEST 邹涛

0924 release版本插拔150次未复现，关闭该bug

#11 - 2022-09-24 19:31 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

#12 - 2022-09-24 19:31 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED