

Figure - Bug #111721

【Figure】【EVT】【EMC】RI01 电磁辐射抗扰度（BCI）：在施加干扰期间，样机断电重启，停止施加干扰后，通过手动操作才能恢复以下功能：1.A2B, 2网口Ping, 3. BT/WIFI 连接。不满足标准要求的自动恢复功能的要求

2022-09-05 14:29 - 项目二组_SD3 曾小文

Status:	CLOSED	Start date:	2022-09-05
Priority:	High	Due date:	
Assignee:	SZ HW Test-曾小文	% Done:	0%
Category:	EE	Estimated time:	0.00 hour
Target version:		Found Version:	2022.08.25
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Release Test		
Description			
RI01 电磁辐射抗扰度（BCI）：在施加干扰期间，样机断电重启，停止施加干扰后，通过手动操作才能恢复以下功能：1.A2B, 2网口Ping, 3. BT/WIFI 连接。不满足标准要求的自动恢复功能的要求			

History

#1 - 2022-09-14 11:32 - CD TPM-申艳艳

- Category set to EE

#2 - 2022-10-21 14:08 - SZ HW Test-曾小文

- Status changed from New to RESOLVED

硬件改方案后复测PASS

#3 - 2022-10-21 14:08 - SZ HW Test-曾小文

- Status changed from RESOLVED to VERIFIED

硬件改方案后复测PASS

#4 - 2022-10-21 14:08 - SZ HW Test-曾小文

- Status changed from VERIFIED to CLOSED

#5 - 2022-10-21 14:08 - SZ HW Test-曾小文

- Assignee changed from SZ-硬件二组_SD3 王苗 to SZ HW Test-曾小文