

Figure - Bug #111735

【Figure】【EVT】【电气性能】E07 电压缓降快升：试验中，电压下降到 9.6V 时，WiFi，蓝牙，视频和以太网功能失效，试验后，重新上电操作，WiFi，蓝牙，视频和以太网功能正常。

2022-09-05 15:48 - 项目二组_SD3 曾小文

| | | | |
|------------------|---------------------------|-------------------|------------|
| Status: | CLOSED | Start date: | 2022-09-05 |
| Priority: | High | Due date: | |
| Assignee: | SZ HW Test-曾小文 | % Done: | 0% |
| Category: | CD-FW | Estimated time: | 0.00 hour |
| Target version: | VX1_MCE_FSE_V2.0_20220930 | Found Version: | 2022.08.25 |
| Need_Info: | -- | Degraded: | -- |
| Resolution: | -- | Verified Version: | |
| Severity: | Major | Fixed Version: | |
| Reproducibility: | Every time | Root cause: | |
| Test Type: | Release Test | | |
| Description | | | |

History

#1 - 2022-09-14 11:32 - CD TPM-申艳艳

- Category set to EE

#2 - 2022-09-16 15:13 - SZ HW Test-曾小文

- Subject changed from 【Figure】【EVT】【电气性能】E07 电压缓降快升：过程中样机中断工作，低压不能工作，无法自己恢复到 【Figure】【EVT】【电气性能】E07 电压缓降快升：试验中，电压下降到9.6V 时，WiFi，蓝牙，视频和以太网功能失效，试验后，重新上电操作，WiFi，蓝牙，视频和以太网功能正常。

#3 - 2022-09-23 16:31 - IOT-SP-TEST 刘颖

- Assignee changed from SZ-硬件二组_SD3 王苗 to CD TPM-申艳艳

Class C需要记忆，软件OS需要做记忆

#4 - 2022-09-26 16:45 - CD TPM-申艳艳

- Category changed from EE to CD-FW

- Assignee changed from CD TPM-申艳艳 to CD- FW-石豪

Hi 石豪，

这个问题用来跟踪和 MCU 连携问题，歇息

#5 - 2022-09-26 18:32 - CD FW-王伟

- Target version set to VX1_MCE_FSE_V2.0_20220930

#6 - 2022-09-27 15:35 - CDTS_TEST 王成

9.27号入代码--石豪

#7 - 2022-09-28 20:48 - CD TPM-申艳艳

- Assignee changed from CD- FW- 石豪 to SZ HW Test- 曾小文

Hi 小文，
代码已经入库，请验证。

#8 - 2022-10-17 10:05 - SZ HW Test- 曾小文

- Status changed from New to ASSIGNED

#9 - 2022-10-17 10:05 - SZ HW Test- 曾小文

- Status changed from ASSIGNED to RESOLVED

#10 - 2022-10-17 10:05 - SZ HW Test- 曾小文

- Status changed from RESOLVED to VERIFIED

#11 - 2022-10-17 10:06 - SZ HW Test- 曾小文

- Status changed from VERIFIED to CLOSED

更新MCU软件，增加记忆功能，复测PASS