

Figure - 开发 Dev #111750
BSP : TSNV : 添加tsnv镜像
2022-09-06 10:21 - CD BSP罗铭

Status:	解决 Resolved	Start date:	2022-09-06
Priority:	Normal	Due date:	2022-09-09
Assignee:	CD BSP-丁武伟	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
添加tsnv镜像			

History

- #1 - 2022-09-06 10:23 - CD BSP罗铭
- Subject changed from 添加tsnv镜像 to BSP : TSNV : 添加tsnv镜像
- #2 - 2022-09-21 11:25 - CD BSP-杜磊
- Assignee changed from CD BSP罗铭 to CD BSP-丁武伟
- #3 - 2022-10-08 11:20 - CD BSP-丁武伟
- Status changed from 进行中 In Progress to 解决 Resolved
- % Done changed from 0 to 100

改修改已经入库：
<https://dev.thundercomm.com/gerrit/c/general/common/+/147728>

#4 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
147728	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	luoming0812@thundersoft.com
BSP: TSNV add nv partitionadd nv partitionTC-RID: 1200-0102001IssueID: TS-R-DF-111750Change-Id: Ie0214f50b82de267b1d3fddca226ccab20c304a2			

#5 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
148126	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-release_evt1	tangjz1204@thundersoft.com
BSP: TSNV add nv partitionadd nv partitionTC-RID: 1200-0102001IssueID: TS-R-DF-111750Change-Id: Ie0214f50b82de267b1d3fddca226ccab20c304a2(cherry			

