

Figure - 开发 Dev #111821

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110126 (New): 【MK】 【AF】 管理总票
【MK】 【FW】 【InputMethod】 【TC-RID: 1201-0200801】
2022-09-08 12:40 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-09-08
Priority:	Normal	Due date:	
Assignee:	CD- FW-石豪	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
■需求列表: 输入法相关的定制			
■提出URL：必填			
■自测case：必填			
■注意点：需要测试注意的前提条件			

History

#1 - 2022-09-15 18:52 - CD- FW-石豪
- Category set to CD-FW
- Status changed from New to 解决 Resolved
- % Done changed from 0 to 100

【测试方法】
系统启动后点击任意带有输入框的应用，点击输入框，弹出输入法为搜狗输入法

【相关提交】
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+147977>
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+148066>

【入库时间】 0910，需要在0911之后的版本验证

#2 - 2022-09-26 18:40 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V2.0_20220930

#3 - 2022-10-10 20:17 - CD FW-王伟
- Status changed from 解决 Resolved to 完成 Closed

#4 - 2022-12-15 15:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170511	general/platform/vendor/hht/apps/Car rierApps	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:InputMethod: update baidu IME versionupdate baidu IME versionTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Id24c7d95d8a94163a6b7f61f4afb785278644f9f			

#5 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147977	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:InputMethod:modify the default IME to SogouChange-Id: I2ce62074ed29ec1b9120f816fc63a6e623347d6eTC-RID: 1201-0200801IssueID: TS-R-DF-111821			

#6 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148066	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:InputMethod:grant permission of Sogou IME if needTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ib3fe8dbb4218ec1e22b6e61a862e23cb1f0b3a42			

#7 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160303	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:InputMethod:add baidu IME for def IMETC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I5cb6b8bf9567ab9011c5328957a8837705b82eb5			

#8 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160306	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:InputMethod:Configure the default IME as Baidu IMETC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I2abfd4be2ef84db1a47c9d993bd9f8359109e585			

#9 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160309	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com

FW:InputMethod:add baidu IMETC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Icf2142545613585b88321920f91700e124fe72bf

#10 - 2023-01-12 14:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
176075	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm-dvt1	caoqg0702@thundersoft.com
AF:InputMethod: delete baidu IME in FTM branchTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ic0e833287d6085aed21888d34be0bf6d9eb29172			

#11 - 2023-03-10 14:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186786	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081	wangxl0510@thundersoft.com
AF:InputMethod: delete baidu IME in FTM branchTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ic0e833287d6085aed21888d34be0bf6d9eb29172(cherry picked from commit e8daf53d28322b2b79db353dbfc3a38e631f9c40)			

#12 - 2023-04-16 11:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193970	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0090	wangxl0510@thundersoft.com
AF:InputMethod: delete baidu IME in FTM branchTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ic0e833287d6085aed21888d34be0bf6d9eb29172(cherry picked from commit e8daf53d28322b2b79db353dbfc3a38e631f9c40)(cherry picked from commit d88efd27ee7a9008b430e5a6ce03bbaeb6bbfa56)			

#13 - 2023-05-03 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197287	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0095	wangxl0510@thundersoft.com

AF:InputMethod: delete baidu IME in FTM branchTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id:
Ic0e833287d6085aed21888d34be0bf6d9eb29172(cherry picked from commit e8daf53d28322b2b79db353dbfc3a38e631f9c40)(cherry picked from commit
d88efd27ee7a9008b430e5a6ce03bbaeb6bbfa56)(cherry picked from commit 183b7b7c02bbde1ab28cea96cf29255b7f935f37)

#14 - 2023-05-15 21:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200271	general/platform/vendor/hht/apps/Car rierApps	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.9TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: Ib5517396990944d8ace8702042dcba4ac98deb0f			

#15 - 2023-05-22 15:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201708	general/platform/vendor/hht/apps/Car rierApps	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.11TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I5b0895c07242e92b97879940447e830facdcfcca			

#16 - 2023-06-05 16:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
204729	general/platform/vendor/hht/apps/Car rierApps	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.13TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: Ic986f56ecc8801e0c58969b5011d18f950f4994c			

#17 - 2023-06-12 17:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
206457	general/platform/vendor/hht/apps/Car rierApps	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.15TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I333a12bed17e881a5017728bf620ddc1902c5573

#18 - 2023-06-19 19:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208466	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
iAF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.16TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I0afeec214b565904b51022a21fcc647ae38e0515			

#19 - 2023-06-20 16:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208696	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:InputMethod: remove aosp imeHide aosp ime by remove add.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: If2c4f405a0dbe296ad73ba3adc6bebd615b5d8fc			

#20 - 2023-06-20 16:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208313	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:InputMethod: hide ime switcher buttonHide ime switcher button.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I4a0acff390b90a68c049abe351fd0e633e4bd9b3			

#21 - 2023-06-20 22:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208864	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.16TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I0afeec214b565904b51022a21fcc647ae38e0515(cherry picked from commit 542481f37b4c8bb66e371f58d8db6c63a6b7123d)

#22 - 2023-06-25 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209477	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.19TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I1791451262b1382ee07912f1e655adb3205bc024			

#23 - 2023-06-25 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209554	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InputMethod: add ime switcher button1.add ime switcher button.2.Change the package name of the default input method.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I76b4238bf6261c44c5734472de169ded9ab74343			

#24 - 2023-06-25 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209571	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InputMethod: Upgrade the database version and update the value of the default input methodTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Id5cf4d45f70313a077b8146dc4614dbc08cb6c3f			

#25 - 2023-06-25 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209683	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.19TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I1791451262b1382ee07912f1e655adb3205bc024(cherry picked from commit b78aa42b2789c3d53bf8b65779ecfea92a801dd1)

#26 - 2023-06-25 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209684	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:InputMethod: add ime switcher button1.add ime switcher button.2.Change the package name of the default input method.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I76b4238bf6261c44c5734472de169ded9ab74343(cherry picked from commit dc64ebe2afb33bee9d1c98ed3c4c721f6a88a9c8)			

#27 - 2023-06-25 21:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209685	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:InputMethod: Upgrade the database version and update the value of the default input methodTC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Id5cf4d45f70313a077b8146dc4614dbc08cb6c3f(cherry picked from commit 609f11869f041e91518d6034909e9245851a8629)			

#28 - 2023-06-26 19:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209882	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:InputMethod: fix aosp ime showingRemove the aosp from the enable list str.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ifd6c605d8bf45dee72643afc9479a2574feb0f2a			

#29 - 2023-06-26 20:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209949	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:InputMethod: fix aosp ime showingRemove the aosp from the enable list str.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: Ifd6c605d8bf45dee72643afc9479a2574feb0f2a(cherry picked from commit 4c719fab3d9e27591f5d42eb6eaf77588367b49)

#30 - 2023-06-28 15:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210496	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:InputMethod: fix aosp ime showing(2)Update the db upgrade logic.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I913704ed70d5af42ac725c3885723f8ee3664c83			

#31 - 2023-06-30 16:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210853	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:InputMethod: fix aosp ime showing(2)Update the db upgrade logic.TC-RID: 1201-0200801IssueID: TS-R-DF-111821Change-Id: I913704ed70d5af42ac725c3885723f8ee3664c83(cherry picked from commit 20aa7b607b0a87921abd8fc9a8c6e1298aa0055d)			

#32 - 2023-07-18 13:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215655	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.20TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I27a21e8ba70275dd362cd31f660534917368c92			

#33 - 2023-07-20 00:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216251	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.20TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I27a21e8ba70275dd362cd31f6605334917368c92(cherry picked from commit 1ff623f46493c080bacd2a0cde61f646c2cbf701)

#34 - 2023-07-31 19:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218991	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.22TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I93cf1fee01f2d2e3d59c2b9c1b96bc2eb3027647			

#35 - 2023-08-01 22:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219409	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.22TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I93cf1fee01f2d2e3d59c2b9c1b96bc2eb3027647(cherry picked from commit d7f5e23c712f79c8a3bd3a6c0c07e526838c2888)			

#36 - 2023-08-22 09:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305043	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.23TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: Ie8e663b24a2347881f475e9a98450556234d579b			

#37 - 2023-08-22 18:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219409	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.22TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I93cf1fee01f2d2e3d59c2b9c1b96bc2eb3027647(cherry picked from commit d7f5e23c712f79c8a3bd3a6c0c07e526838c2888)

#38 - 2023-08-22 18:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305338	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.23TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: Ie8e663b24a2347881f475e9a98450556234d579b(cherry picked from commit e443237a18d2498968864b39af9b9355c82365fd)			

#39 - 2023-09-26 19:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316321	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.24TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I750ba2592b62df387824c4a5e945f5269f240298			

#40 - 2023-10-07 17:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317346	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.24TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I750ba2592b62df387824c4a5e945f5269f240298(cherry picked from commit f8e9be911c9f58b4686679f2c4875e0f61bfbc2b)			

#41 - 2023-11-17 16:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329085	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.25TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I9c497fb5aec610cd2e8c4adbef98cbaf26de1e53

#42 - 2023-11-20 13:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329432	general/platform/vendor/hht/apps/CarrierApps	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Preinstall: update baidu IME versionupdate baidu IME version = 10.6.1003.25TC-RID: 1201-0204401IssueID: TS-R-DF-111821Change-Id: I9c497fb5aec610cd2e8c4adbef98cbaf26de1e53(cherry picked from commit 2f4a45dafcfc3f9af20e50b3721ee2cf0889eed)			