

Figure - Bug #111840

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 111713 (New): BSP-V1.0-OTA升级

【BSP】【EVT】【OTA】【必现】本地OTA升级失败过一次后，无法重新开始升级；失败的状态没有清除

2022-09-08 22:11 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-09-08
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925	Found Version:	VB-1187-20220908
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Bring Up Test		
Description			
前置条件： 1、DUT各模块功能正常且处于开机状态 2、板子OTA升级失败过一次 操作步骤： 1、将ota升级包push到指令目录后，执行升级命令 实际结果： 1、无法进行OTA升级，报错提示 预期结果： 1、可以正常进行OTA升级			

History

#1 - 2022-09-08 22:12 - SZTS_TEST 邹涛
- File 中科创达软件股份有限公司20220908-221202.jpg added
#2 - 2022-09-08 22:31 - CD BSP-唐金泽
- Assignee changed from CD BSP-唐金泽 to CD BSP 叶鹏
后续请叶鹏进行功能完善
#3 - 2022-09-14 10:34 - CD BSP 叶鹏
- Assignee changed from CD BSP 叶鹏 to SZTS_TEST 邹涛
- Severity changed from Critical to Normal
经调查android代码发现并没有找到可能出现该现象的地方，本地多次测试也没有发现该现象；经沟通发现是执行了adb remount之后导致的，要升级的设备是不能执行该命令的，执行该命令会导致设备无法升级，次现象不为bug，驳回。
#4 - 2022-09-14 10:40 - CD BSP 叶鹏
- Status changed from New to RESOLVED

经调查android代码发现并没有找到可能出现该现象的地方，本地多次测试也没有发现该现象；经沟通发现是执行了adb remount之后导致的，要升级的设备是不能执行该命令的，执行该命令会导致设备无法升级，次现象不为bug，驳回。

#5 - 2022-09-14 11:30 - CD'TPM-申艳艳

- Category set to BSP
- % Done changed from 0 to 100

#6 - 2022-09-14 14:53 - SZTS_TEST 邹涛

测试误操作使用 adb remount导致

#7 - 2022-09-14 14:53 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

#8 - 2022-09-14 14:54 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED

#9 - 2022-09-15 18:41 - CDTS-TEST 周婷

- Target version set to VXL_MCE_FSE_V1.0_update_20220925

Files

logcat.txt	5.14 MB	2022-09-08	SZTS_TEST 邹涛
中科创达软件股份有限公司20220908-221202.jpg	72.9 KB	2022-09-08	SZTS_TEST 邹涛