

Figure - Bug #111986

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】【EVT】【设置】切换深色模式、调节字体大小之后会闪退

2022-09-15 17:24 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-15
Priority:	Normal	Due date:	2022-09-21
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220915
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		

Description
【前提条件】 无
【测试步骤】 1、进入设置 -显示 2、打开深色模式 3、调节字体大小
【预期结果】 2、直接进入深色模式 3、字体大小随调节发生改变
【实际结果】 2、点击开启深色模式按钮后，闪退至主界面 3、调节字体大小后，闪退至主界面
【复现率】 必现

History

- #1 - 2022-09-16 09:57 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
- #2 - 2022-09-21 16:20 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- #3 - 2022-09-21 16:23 - CD AF-陈羽杰
- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 80
- Resolution changed from -- to FIXED

■ Current conclusion
问题已经通过代码修复

■ My analysis

选择字体或者主题模式后，重走生命周期时，为作判空处理，导致carsh

■ Next Action

本地修改验证

#4 - 2022-09-21 16:25 - CD AF-陈羽杰

- Due date set to 2022-09-21
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
- % Done changed from 80 to 100
- Degrated changed from -- to No
- Root cause set to 编码问题

■ Current conclusion

问题已经通过代码修复

■ My analysis

切换主题或者字体后，生命周期重走，prefence 为空，导致crash

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/150404>

#5 - 2022-09-23 10:21 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#6 - 2022-09-23 10:22 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150404	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Modify Settings1.Add external click compatibility2.FIX BUG IssueID 1120173.FIX BUG IssueID 1120284.FIX BUG IssueID 111986TC-RID: 1201-0201801IssueID: TS-R-DF-111986Change-Id: I89eb816a81331ad9559868004809e0965bb264c4			