

Figure - 开发 Dev #112096

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务

【MK】【008】【BOOT】【TC-RID:1200-0100806】Board ID

2022-09-22 11:14 - CD BSP-丁武伟

Status:	完成 Closed	Start date:	2022-09-22
Priority:	Normal	Due date:	2022-10-30
Assignee:	CD BSP-余霄	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
Bord ID 兼容			

History

- #1 - 2022-09-23 15:31 - CD BSP-杜磊
- Status changed from New to 解决 Resolved
 - % Done changed from 0 to 100
- #2 - 2022-09-26 10:49 - CD BSP-杜磊
- Status changed from 解决 Resolved to 完成 Closed

验证方法：

1. VX1和VC1的lcd能够正常显示
2. VX1和VC1的tp能够正常滑动
3. adb shell getprop ro.boot.board_id 能读取ID信息

ftp://cdiot@192.168.87.46/Pre_figure/DailyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/NULL/20220923/0413/FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220923.alpha.zip

验证结果：

PASS

- #3 - 2022-10-25 10:36 - CD BSP-唐金泽
- Due date set to 2022-10-30
 - Status changed from 完成 Closed to 进行中 In Progress
 - Assignee changed from CD BSP-杜磊 to CD BSP-余霄
 - Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V3.0_20221030
 - % Done changed from 100 to 80

增加EVT2以后版本的硬件ID支持的display 和TP功能

- #4 - 2022-11-03 11:02 - CD BSP-余霄

code已完成，待验证

<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/157962>

#5 - 2022-11-08 16:39 - CD BSP-余霄

后续code均使用该TOPIC
DVT PVT MP均已适配完成

https://dev.thundercomm.com/gerrit/q/topic:FIGURE_DISPLAY_BU

#6 - 2022-11-18 18:55 - CD BSP-余霄

- Status changed from 进行中 In Progress to 解决 Resolved
- % Done changed from 80 to 100

VX1 VC1代码验证完成，已入库

#7 - 2022-11-29 10:11 - CD BSP-唐金泽

- Status changed from 解决 Resolved to 完成 Closed

#8 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149317	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:BOOT: Add the board_id support for figureAdd different hardware version dtsTC-RID: 1200-0100806IssueID: TS-R-DF-112096Change-Id: Icf97ea75ef950cf1f57eba5db8fde2a9d4e4dfa			

#9 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150159	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:BOOT: Add the board_id support for figureAdd the board_id system propTC-RID: 1200-0100806IssueID: TS-R-DF-112096Change-Id: I8f6facb51f7d97d0d18f04ade666cddf7443ff50			

#10 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157962	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com

BSP:BOOT: Add the board_id support for figure DVT PVT and MPAdd different hardware version dts for DVT PVT and MPTC-RID: 1200-0100806IssueID: TS-R-DF-112096Change-Id: I02a4816100909cf96fe235f193e7d5296336697c

#11 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163171	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:BOOT: Add the board_id support for figureAdd board_id info update in PlatformInfoDxe.TC-RID: 1200-0100806IssueID: TS-R-DF-112096Change-Id: I25dd2808239001c36ed3be8f3b25ff4cc20cbdee(cherry picked from commit 56da012469318632bed7f8a3f7d7e014f134e131)			

#12 - 2023-03-22 18:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187342	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:BOOT: Modify board_id for DVT2Modify board_id for DVT2VX1 Board_Id: 0x02VC1 Board_Id: 0x12TC-RID: 1200-0100806IssueID: TS-R-DF-112096Change-Id: I5341e7bbff9e03e4efc12dbf285400e1ac0f8661			