

Figure - Bug #112132

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】系统-日期与时间-时区-时区-点击具体时区，闪退回主界面

2022-09-26 13:48 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-26
Priority:	High	Due date:	2022-09-29
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220924.alpha
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220924.alpha
Severity:	Normal	Fixed Version:	2022-09-27
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、进入设置 系统-日期与时间-时区 2、点击时区			
【预期结果】 2、可以选择具体时区			
【实际结果】 2、点击具体时区后之后，闪退回主界面			
【复现率】 必现			

History

- #1 - 2022-09-26 16:40 - CD TEST-方永红
- Found Version changed from FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924.alpha_0019 to FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220924.alpha
- #2 - 2022-09-27 10:23 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
- #3 - 2022-09-27 10:30 - CD TEST-方永红
- Priority changed from Normal to High
- #4 - 2022-09-27 19:35 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- #5 - 2022-09-27 19:56 - CD AF-陈羽杰
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED

- Degrated changed from -- to No
- Fixed Version set to 2022-09-27
- Root cause set to 编码问题

■ Current conclusion

问题已经通过代码修复

■ My analysis

由于双屏显示，与原生逻辑冲突，导致原生fragment关闭掉了宿主Activity。

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/152209>

#6 - 2022-09-28 14:19 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220928.alpha_0022

#7 - 2022-09-28 14:19 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#8 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152209	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix TimeZone Bug1.Click the specific time zone to flash back to the main interfaceTC-RID: 1201-0201809IssueID: TS-R-BUG-112132Change-Id: I1829cc26b5e3e4cc16330febd079de8e68552d96			

Files

时区-时区.log	10.2 KB	2022-09-26	CD TEST-方永红
-----------	---------	------------	-------------