

Figure - Bug #112135

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111043 (New): AF-V2.0-自动背光

【AF】 【EVT】 【自动背光】 设置 - 显示中的 “ 自动背光开关 ” 没有即时同步状态

2022-09-26 14:12 - CD Test赵飞

Status:	CLOSED	Start date:	2022-09-26
Priority:	Normal	Due date:	2022-09-30
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220928
Severity:	Minor	Fixed Version:	2022-09-28
Reproducibility:	Every time	Root cause:	因为Settings中没监听数据库值的变化,没有自动切换
Test Type:	IT		

Description	
测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924.alpha_0019	
【前提条件】 1、设备已开机	
【测试步骤】 1、进入设置 - 显示 2、向下滑动屏幕打开控制中心 3、点击打开或关闭 “ 自动亮度 ” 开关 4、点击屏幕任意空白处退出控制中心 5、查看显示页面中 “ 自动调节亮度 ” 开关状态	
【预期结果】 5、“ 自动调节亮度 ” 开关立即同步控制中心开关状态，与之保持一致	
【实际结果】 5、“ 自动调节亮度 ” 开关没有立即同步控制中心开关状态，需要退出当前页面再进入后才会显示正确的状态	
【复现率】 5/5	
【Log】 Log见附件	

History

- #1 - 2022-09-26 17:48 - CDFW-王伟
- Assignee changed from CD FW-王伟 to CD FW-程天颖
- #2 - 2022-09-26 18:33 - CDFW-王伟
- Target version set to VX1_MCE_FSE_V2.0_20220930
- #3 - 2022-09-27 20:22 - CDFW-程天颖
- Status changed from New to RESOLVED
- Assignee changed from CD FW-程天颖 to CD Test赵飞

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220928.alpha_0019
- Fixed Version set to 2022-09-28
- Root cause set to 因为Settings中没监听数据库值的变化,没有自动切换,加上监视器即可

■ Current conclusion

已解决

■ My analysis

因为Settings中没监听数据库值的变化,没有自动切换,加上监视器即可

■ Next action / ■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+152239>

#4 - 2022-09-28 15:41 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220928.alpha_0022

验证结果：PASS

#5 - 2022-09-28 15:41 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

#6 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
152239	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:Settings:Auto Brightness cant sync Control Center1.fixed Auto Brightness cant sync Control CenterTC-RID: 1201-0201806IssueID: TS-R-BUG-112135Change-Id: Ibf6fb0fb450f985ecc1f7471d86779314a528554			

Files

logcat.txt	3.57 MB	2022-09-26	CD Test赵飞
screen-20220924-032426.mp4	9.83 MB	2022-09-26	CD Test赵飞