

Figure - Bug #112199

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】 【EVT】 【设置】 声音-媒体音量调节精确度不高，只能一段一段调节

2022-09-28 15:54 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-28
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_update_20221012	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220928
Need_Info:	--	Degrated:	--
Resolution:	WORKSFORME	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	原生设计,不推荐修改
Test Type:	IT		
Description			
【前提条件】 无			
【测试步骤】 1、进入设置 - 声音 2、调节媒体音量			
【预期结果】 2、能够调节，且调节精确度较高（可以参考控制中心的音量调节的精确度）			
【实际结果】 2、只能一段一段调节			
【复现率】 必现			

History

#1 - 2022-09-28 16:15 - CD FW-王伟

- Assignee changed from CD FW-王伟 to CD FW-鲁凯峰

#2 - 2022-09-28 16:30 - CD FW-鲁凯峰

- Status changed from New to RESOLVED

- Assignee changed from CD FW-鲁凯峰 to CD TEST-方永红

- Resolution changed from -- to WORKSFORME

- Root cause set to 原生设计,不推荐修改

原生Settings就是这样设计的,音量调节就是一节一节的,不建议修改

#3 - 2022-09-28 16:32 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- % Done changed from 0 to 100

#4 - 2022-09-28 16:33 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

媒体音量.log	15.7 KB	2022-09-28	CD TEST-方永红
----------	---------	------------	-------------