## Figure - Bug #112541

## 【Figure】【TC8】【IOP】样件未实现休眠唤醒功能,OABR\_LINKUP\_03唤醒 DUT未测试

2022-10-13 10:21 - SZ HW Test-曾小文

Status: **CLOSED** Start date: 2022-10-13 Priority: Due date: Normal Assignee: SZ HW Test-曾小文 % Done: 0% Category: **BSP** Estimated time: 0.00 hour Target version: Need\_Info: Found Version: 2022.10.09 Resolution: Degrated: Severity: Verified Version: Normal Reproducibility: Fixed Version: Every time Root cause: Test Type: Release Test

Description

需增加休眠唤醒功能

## History

#1 - 2022-10-17 10:39 - SZ HW Test-曾小文

- Status changed from New to RESOLVED

产品断开KL15可以休眠,复测PASS

#2 - 2022-10-17 10:39 - SZ HW Test-曾小文

- Status changed from RESOLVED to VERIFIED
- Assignee changed from CD BSP-杜磊 to SZ HW Test-曾小文

#3 - 2022-10-17 10:39 - SZ HW Test-曾小文

- Status changed from VERIFIED to CLOSED

产品断开KL15可以休眠,复测PASS

2025-07-04 1/1