

Figure - Bug #112562

【AF】 【EVT1】 【高合动画】 【必现】 设备上电开机没有高合汽车动画

2022-10-14 14:07 - CDTS_TEST 刘勇

Status:	CLOSED	Start date:	2022-10-14
Priority:	Normal	Due date:	
Assignee:	CD FW 曹覃刚	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Need_Info:	--	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug 0.0.0.20221014
Resolution:	FIXED	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	IT	Root cause:	因开机启动问题，之前临时将开机动画去掉，现已加回

Description
【前提条件】 1.设备链接显示器
【测试步骤】 1.设备已开机 2.查看开机动画
【预期结果】 2.开机无安卓动画，有高合汽车动画
【实际结果】 2.开机有安卓动画，无高合汽车动画
【复现率】 100%
【Log】 Log见附件

History

- #1 - 2022-10-17 14:51 - CD APP-王营
- Assignee changed from CD APP-王营 to CD FW 曹覃刚
- #2 - 2022-10-18 13:49 - CDTS_TEST 刘勇
- Category set to BSP
- #3 - 2022-10-19 10:01 - CD FW-王伟
- Category changed from BSP to CD-FW
- #4 - 2022-10-24 13:39 - CD FW 曹覃刚
- Status changed from New to RESOLVED
- Resolution changed from -- to FIXED
- Root cause set to 因开机启动问题，之前临时将开机动画去掉，现已加回

此问题已修复，代码已入库

#5 - 2022-10-25 17:23 - CDTS_TEST 刘勇

【HW】 EVT2-VX1
【SW】 FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221025.alpha_0039
【前提条件】 无
【操作步骤】
1.DUT烧录10月25号的Release的User版本
2.给板子下上电
【实际结果】
2.设备启动，有高合开机动画
【测试次数】 5/5
【验证结果】 PASS,验证通过

#6 - 2022-10-28 20:00 - CDTS_TEST 刘勇
- Status changed from RESOLVED to VERIFIED

#7 - 2022-10-28 20:00 - CDTS_TEST 刘勇
- Status changed from VERIFIED to CLOSED

#8 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157078	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:SystemOptimization: Perform synchronization after bootPerform synchronization after bootTC-RID: 1201-0205101IssueID: TS-R-DF-112562Change-Id: I78cc6e3db14b22292587ddd8d973592e7fd65f4f			

Files

Boot_Animation.txt	470 KB	2022-10-14	CDTS_TEST 刘勇
--------------------	--------	------------	--------------