

Figure - Bug #112578

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】【图库】使用屏幕截图截一张图，点击图片旁边的分享按钮，再点击弹出页面的编辑按钮，会造成闪退，无法进入编辑模式，重复操作会导致图库崩溃

2022-10-14 19:16 - CD TEST-方永红

|                              |                           |                   |                                                        |
|------------------------------|---------------------------|-------------------|--------------------------------------------------------|
| Status:                      | CLOSED                    | Start date:       | 2022-10-14                                             |
| Priority:                    | High                      | Due date:         |                                                        |
| Assignee:                    | CD TEST-方永红               | % Done:           | 100%                                                   |
| Category:                    | CD-APP                    | Estimated time:   | 0.00 hour                                              |
| Target version:              | VX1_MCE_FSE_V3.0_20221030 | Found Version:    | FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221023 |
| Need_Info:                   | --                        | Degrated:         | No                                                     |
| Resolution:                  | FIXED                     | Verified Version: | FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023      |
| Severity:                    | Normal                    | Fixed Version:    | 2022-09-22                                             |
| Reproducibility:             | Every time                | Root cause:       | AOSP问题                                                 |
| Test Type:                   | IT                        |                   |                                                        |
| Description                  |                           |                   |                                                        |
| 【前提条件】                       |                           |                   |                                                        |
| 1、设备已开机                      |                           |                   |                                                        |
| 【测试步骤】                       |                           |                   |                                                        |
| 1、进入控制中心                     |                           |                   |                                                        |
| 2、点击屏幕截图                     |                           |                   |                                                        |
| 3、点击出现的截图的旁边的分享按钮            |                           |                   |                                                        |
| 4、点击弹出页面的编辑按钮                |                           |                   |                                                        |
| 【预期结果】                       |                           |                   |                                                        |
| 4、点击之后进入图片编辑模式               |                           |                   |                                                        |
| 【实际结果】                       |                           |                   |                                                        |
| 4、会造成闪退，无法进入编辑模式，重复操作会导致图库崩溃 |                           |                   |                                                        |

History

#1 - 2022-10-20 18:22 - CD APP-黄棚

- Assignee changed from CD APP-王营 to CD APP-黄棚
- % Done changed from 0 to 100
- Degrated changed from -- to No
- Fixed Version set to 2022-09-21
- Root cause set to AOSP问题

Current conclusion

已定位问题，SystemUI screenshot在创建ShareAction的时候并没有将URL传递给setData,而是给了ClipData. Gallery2获取是通过getData获取的，这样的话肯定拿到的uri就为空了

My analysis

修改galler2，如果getData为空就去判断getClipData是否有值

Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Gallery2/+156636>

#2 - 2022-10-21 15:04 - CD APP-黄棚  
- Fixed Version changed from 2022-09-21 to 2022-09-22

#3 - 2022-10-21 15:09 - CD APP-黄棚  
- Assignee changed from CD APP-黄棚 to CD TEST-方永红

#4 - 2022-10-21 16:06 - CD APP-黄棚  
- Status changed from New to ASSIGNED

#5 - 2022-10-21 16:06 - CD APP-黄棚  
- Status changed from ASSIGNED to RESOLVED  
- Resolution changed from -- to FIXED

#6 - 2022-10-24 10:16 - CD TEST-方永红  
- Status changed from RESOLVED to VERIFIED  
- Verified Version set to FlatBuild\_VX1\_MCE\_xx.xx\_FSE.D.user.0.0.0.20221023.alpha

10.24 验证关闭

#7 - 2022-10-24 10:16 - CD TEST-方永红  
- Status changed from VERIFIED to CLOSED

#8 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                              | Project                                 | Branch                                    | Uploader                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-------------------------------------------|-------------------------------|
| 156636                                                                                                                                                                          | general/platform/packages/apps/Gallery2 | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | huangpeng1216@thundersoft.com |
| FW:Gallery2: Fix Gallery2 edit mode crash bug1. Fix Gallery2 edit mode crash bugTC-RID: 1201-0300701IssueID: TS-R-DF-112578Change-Id: I8e9084e0bd85339095c34d5ebd7c3e2e98b4f4d2 |                                         |                                           |                               |

Files

|                                       |         |            |             |
|---------------------------------------|---------|------------|-------------|
| Phone-5221FC0 2022-10-14 18-29-49.mp4 | 17 MB   | 2022-10-14 | CD TEST-方永红 |
| 141914.txt                            | 8.86 MB | 2022-10-14 | CD TEST-方永红 |