

Figure - Bug #112770

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】【声音】触摸提示音功能和相关UI应该被裁剪掉

2022-10-21 16:13 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-21
Priority:	Normal	Due date:	2022-10-21
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221023
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	AOSP问题
Test Type:	IT		

Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置-声音			
2、观察页面显示			
【预期结果】			
2、无触摸提示音及相关功能			
【实际结果】			
2、存在触摸提示音及相关功能			

History

#1 - 2022-10-21 18:09 - CD AF-陈羽杰

- Due date set to 2022-10-21
- Status changed from New to ASSIGNED

#2 - 2022-10-21 18:32 - CD AF-陈羽杰

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Root cause set to AOSP问题

■ Current conclusion

本地已添加验证

■ My analysis

功能未覆盖

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+157165>

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+157159>

#3 - 2022-10-21 18:33 - CD AF-陈羽杰
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红

#4 - 2022-10-24 10:19 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023.alpha

10.24 验证关闭

#5 - 2022-10-24 10:19 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#6 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157159	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	yujie.chen@thundersoft.com
AF:Settings: Cut Touch Sound effect1.Cut SoundSettings Touch Sound effectTC-RID: 1201-0201805IssueID: TS-R-BUG-112770Change-Id: I175821794c21431b522e2c916f5cee1d0160d021			

#7 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157165	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	yujie.chen@thundersoft.com
AF:Settings: Cut Touch Sound effect1.Cut SoundSettings Touch Sound effectTC-RID: 1201-0201805IssueID: TS-R-BUG-112770Change-Id: I7a1ea5b8ada28659c7032f3c5441a92dfa5f26b6			

Files

chum提示音.png	128 KB	2022-10-21	CD TEST-方永红
-------------	--------	------------	-------------