

Figure - Bug #112800

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】进入WIFI列表页面->返回桌面->回到设置WIFI列表页面->进入一个WiFi连接页面->点击左上角返回，直接回到桌面

2022-10-24 14:30 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-24
Priority:	Normal	Due date:	2022-10-24
Assignee:	CD AF-陈羽杰	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221025
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221025
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
2、后台无进程			
【测试步骤】			
1、进入设置，打开WLAN			
2、进入WIFI列表页面			
3、返回桌面			
4、回到设置WIFI列表页面			
5、进入一个WiFi连接页面			
6、点击左上角返回			
【预期结果】			
6、返回WIFI连接页面			
【实际结果】			
6、直接回到桌面			

History

- #1 - 2022-10-24 15:23 - CD TEST-方永红
- Target version changed from VX1_MCE_FSE_V3.0_update_20221130 to VX1_MCE_FSE_V3.0_20221030
- #2 - 2022-10-24 16:23 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- #3 - 2022-10-24 16:25 - CD AF-陈羽杰
- Due date set to 2022-10-24
 - Status changed from ASSIGNED to RESOLVED
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Root cause set to 编码问题

■ Current conclusion
本地已修复验证
■ My analysis
离开Settings时清除了Fragments栈
■ Submit URL
下一步做什么，或者提交是什么，写明验证步骤
<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+/157502>

#4 - 2022-10-25 16:02 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221025.alpha_0039

10.25 验证10次未复现

#5 - 2022-10-25 16:02 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#6 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157502	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix Exception returned from the wifi page1.Exception returned from wifi page Enter WIFI list page ->Return to desktop ->Return to setting WIFI list page ->Enter a WiFi connection page ->Click the upper left corner to return to the desktop directlyTC-RID: 1201-0201801IssueID: TS-R-BUG-112800Change-Id: I4e01872ea2ea60669cafde9793f5bac6672c89d0			

Files			
1428.txt	8.33 MB	2022-10-24	CD TEST-方永红