

Figure - Bug #112830

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】进入系统-手势-手势导航旁边的设置页面，再向上滑动直接进入多任务管理器，此时全部清除功能失效且无法单击退出多任务管理器

2022-10-24 17:41 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-24
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	Android12新特性引起的，不受信任的触摸事件将被
Test Type:	IT		
Description			
【前提条件】 1、设备已开机 【测试步骤】 1、进入设置-系统-手势-手势导航 2、点击手势导航旁边的设置按钮，进入手势设置页面 3、向上滑动直接进入多任务管理器 4、点击屏幕下方的清除按钮 5、单击多任务管理器空白处 【预期结果】 4、设置及其他后台应用均被清除 5、退出多任务管理器 【实际结果】 4、设置及其他后台应用未被清除 5、没有退出多任务管理器 【复现率】 必现			

History

#1 - 2022-10-25 11:24 - CD FW 曹覃刚

- % Done changed from 0 to 20

点击事件被丢弃了，我们将进一步分析

10-25 11:19:00.110 1012 1671 W InputDispatcher: Untrusted touch due to occlusion by com.android.settings/1000 (obscuring opacity = 1.00, maximum allowed = 0.80)

10-25 11:19:00.110 1012 1671 D InputDispatcher: Stack of obscuring windows during untrusted touch (1265, 903):

10-25 11:19:00.110 1012 1671 D InputDispatcher: * type=2038, package=com.android.settings/1000, id=251, mode=USE_OPACITY, alpha=1.00, frame=[0,0][2380,1020], touchableRegion=[0,0][2380,1020], window={b6d7232 BackGestureIndicatorView}, flags={NOT_FOCUSABLE | NOT_TOUCHABLE | HARDWARE_ACCELERATED | DRAWS_SYSTEM_BAR_BACKGROUNDS}, inputFeatures={0x0}, hasToken=true, applicationInfo.name=, applicationInfo.token=<null>

10-25 11:19:00.111 1012 1671 D InputDispatcher: * [TOUCHED] type=FIRST_APPLICATION_WINDOW, package=com.android.launcher3/10087, id=255, mode=USE_OPACITY, alpha=1.00, frame=[0,0][2380,1020], touchableRegion=[0,0][2380,1020], window={41017a9 com.android.launcher3/com.android.launcher3.uioverrides.QuickstepLauncher}, flags={NOT_TOUCH_MODAL | LAYOUT_IN_SCREEN | LAYOUT_INSET_DECOR | SHOW_WALLPAPER | SPLIT_TOUCH | HARDWARE_ACCELERATED | DRAWS_SYSTEM_BAR_BACKGROUNDS}, inputFeatures={0x0}, hasToken=true, applicationInfo.name=ActivityRecord{4a0335c u0 com.android.launcher3/.uioverrides.QuickstepLauncher t173}, applicationInfo.token=0xb400007c3be0bbd0

10-25 11:19:00.111 1012 1671 W InputDispatcher: Dropping untrusted touch event due to com.android.settings/1000

- #2 - 2022-10-25 14:18 - CD FW 曹覃刚
- Status changed from New to RESOLVED
 - Resolution changed from -- to FIXED
 - Root cause set to Android12新特性引起的，不受信任的触摸事件将被屏蔽，添加了判断条件，让设定不被屏蔽

提交已入库

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/native/+/157719>

- #3 - 2022-10-26 14:14 - CD TEST-方永红
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
 - % Done changed from 20 to 100
 - Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026.alpha

10.26 验证关闭

- #4 - 2022-10-26 14:16 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

- #5 - 2022-10-26 14:16 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

- #6 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157719	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Settings: Fix the problem of touch and click failureThe new feature of android12, untrusted touch events will be blockedWe have added a judgment condition, the setting will not be blockedTC-RID: 1201-0201809IssueID: TS-R-BUG-112830Change-Id: Ia80bf9b1c902d319121d21601b7da31a4b7453db			

Files			
Phone-STs40X190122 2022-10-24 17-18-01.mp4	14.9 MB	2022-10-24	CD TEST-方永红
1737.txt	1.94 MB	2022-10-24	CD TEST-方永红