

Figure - Bug #113247

【EVT1】【BSP】【Power】【必现】整车上下电，板子未正常启动卡在android动画界面，adb可以使用

2022-10-28 13:46 - CDTS_TEST 刘勇

Status:	CLOSED	Start date:	2022-10-28
Priority:	High	Due date:	
Assignee:	CDTS_TEST 刘勇	% Done:	100%
Category:	客户工厂bug跟踪	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	见附件图片-imav2__0
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	2022-10-31
Reproducibility:	Every time	Root cause:	原生问题 修复方案已入库于10/21, 请使用10/21
Test Type:	IT		

Description

【前提】
刷机烧录版本
【操作步骤】
整车上电

【实际结果】
板子未正常启动，卡在Andorind动画界面
【期望结果】
板子正常启动，动画流畅

History

- #1 - 2022-10-28 13:48 - CDTS_TEST 刘勇
- Category changed from 客户jira bug to 客户工厂bug跟踪
- #2 - 2022-10-28 14:47 - CD BSP-唐金泽
- Status changed from New to ASSIGNED
- Assignee changed from CD BSP-唐金泽 to CD FW 曹覃刚

从现象和dmesg上看，和之前烧录Android系统未启动就断电，导致系统无法启动一致。
AF同事也帮忙check下log呢？是否属于同根问题

- #3 - 2022-10-28 20:09 - CDTS_TEST 王成
- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115
- #4 - 2022-10-31 15:53 - CD FW 曹覃刚
- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Root cause set to 原生问题
- 修复方案已入库于10/21, 请使用10/21之后的版本进行测试

已修复，提交如下
入库于10/21, 请使用10/21之后的版本进行测试

#5 - 2022-11-01 17:39 - CD FW 曹覃刚

- Degrated changed from -- to No
- Fixed Version set to 2022-10-31

#6 - 2022-11-02 15:49 - CD BSP-唐金泽

- Assignee changed from CD FW 曹覃刚 to CDTS_TEST 刘勇

#7 - 2022-11-07 15:34 - CDTS_TEST 刘勇

【HW】EVT2-VC1
【SW】FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211050252
【前提】
刷机烧录版本
【操作步骤】
整车上电
【实际结果】
板子正常启动，高合动画流畅。无Andorid动画
【测试次数】5次
【验证结果】PASS，验证通过

#8 - 2022-11-07 15:35 - CDTS_TEST 刘勇

- Status changed from RESOLVED to VERIFIED

#9 - 2022-11-07 15:35 - CDTS_TEST 刘勇

- Status changed from VERIFIED to CLOSED

Files				
dmesg.txt	935 KB	2022-10-28	CDTS_TEST 刘勇	
logcat.txt	5.75 MB	2022-10-28	CDTS_TEST 刘勇	
img_v2_50aa4fbe-75e0-449a-8310-5e54b9ddda5g.jpg	112 KB	2022-10-28	CDTS_TEST 刘勇	