

Status:	CLOSED	Start date:	2022-11-01
Priority:	Normal	Due date:	
Assignee:	SZ HW Test-曾小文	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	依赖硬件的bugList	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.00.0042.X101.zip
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Release Test		
Description			
有安卓投屏端口，但是无高通端口，无法测试，RF硬件31号修改了新参数，未合入版本			

History

- #1 - 2022-11-01 17:24 - CD BSP-唐金泽
- Target version set to 依赖硬件的bugList
- RF硬件31号修改了新参数，已合入版本，
- 请使用如下版本，进行验证（已飞书发送至硬件）
- http://cdiot@192.168.87.46/Pre_figure/ReleaseBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/NULL/20221101/0743/FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0042.X101.zip
- #2 - 2022-11-01 17:26 - CD BSP-唐金泽
- Status changed from New to NEED_INFO
- Assignee changed from CD BSP-唐金泽 to SZ HW Test-曾小文
- % Done changed from 0 to 100
- 已验证过adb和高通901d端口。
- 请帮忙明确无法读取高通端口哪个端口的具体期待
- #3 - 2022-11-02 13:30 - SZ HW Test-曾小文
- Status changed from NEED_INFO to RESOLVED
- #4 - 2022-11-02 13:30 - SZ HW Test-曾小文
- Status changed from RESOLVED to VERIFIED
- FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0042.X101 版本已解决该问题
- #5 - 2022-11-02 13:31 - SZ HW Test-曾小文
- Status changed from VERIFIED to CLOSED